HISTORIC PRESERVATION COMMISSION AGENDA ITEM EXECUTIVE SUMMARY Agenda Item Title/Address: Proposal: Window replacement Petitioner: Please check appropriate box (x) PUBLIC HEARING MEETING 8/7/13 AGENDA ITEM CATEGORY:

 \mathbf{X}

ATTACHMENTS:

X

2003 photo showing previous windows

Preliminary Review

Discussion Item

Photo showing installed replacement windows

Certificate of Appropriateness (COA)

EXECUTIVE SUMMARY:

Windows on the house at 120 N. 4th St. were replaced without a permit. By the time the Building Division was alerted, all of the windows had already been installed and the contractor was completing the installation.

Façade Improvement Plan

Commission Business

Landmark/District Designation

Attached is a photo of the building from 2003 showing the previous windows, which appear to have been covered in aluminum storm windows.

The replacement windows appear to be vinyl double hung, with the exception of the front picture window, which is a fixed pane. The property owner has not yet submitted information for a building permit and no further information on the windows has been provided.

The house is rated in the Architectural Survey as Contributing and appears to be sided in vinyl.

RECOMMENDATION / SUGGESTED ACTION:

Provide feedback and recommendations for approval of the COA.



ARCHITECTURAL SURVEY

CENTRAL HISTORIC DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 120 N 4th St

1994 Photo Roll: 12 Negative: 29, 30




Photo: Aug. 2003

ARCHITE	CTURAL	SIGNIFI	CANCE

- ☐ Significant
- ♦ Contributing
- □ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ♦ Excellent
- □ Good
- □ Fair
- □ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	National Folk	Exterior Walls (Current):	Clapboard	
Architectural Features:		Exterior Walls (Original):	Clapboard	
Date of Construction: Source:	1910 Assessor	Foundation: Roof Type/Material:	Asphalt shingle	_
Overall Plan Configuration:		Window Material/Type:		_

ARCHITECTURAL FEATURES: Front gable and wing. Shingles at gable, clapboard siding below. Mansard type roof over first floor picture window with art glass transom.

ALTERATIONS: Minor alteration to first floor.



