

ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY				BUILDING CONDITION
	1	2	3	☐ Excellent: Well-maintained
☐ Unaltered				☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐
☐ Minor Alteration				☐ Fair: Major repairs needed
☐ Major Alteration				☐ Poor: Deteriorated
 ✓ Additions Sensitive to original Insensitive to original 1: first floor; 2: upper floors; 		□ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □		ARCHITECTURAL DESCRIPTION Style: Utilitarian Date of Construction: 1920-1950 Source: Field Observation Features:
ARCHITECTURAL SIGNIFICANCE				Brick buildings with stone parapet cap.
☐ Significant				
☐ Contributing				
☐ Non-Contributing				



ROLL NO. 18

NEGATIVE NO. 21

Address:

State Street,west of Route 31 Car Wash

Representation in Existing Surveys:

- ☐ Federal
- ☐ State
- ☐ County
- ☐ Local

Block No. 3

Building No. 2

SURVEY DATE:

MAY 1994