

# ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL INTEGRITY				BUILDING CONDITION
	1	2	3	☐ Excellent: Well-maintained
<b>☑</b> Unaltered				☐ Good: Minor maintenance needed
☐ Minor Alteration				☐ Fair: Major repairs needed
☐ Major Alteration				☐ Poor: Deteriorated
□ Additions Sensitive to original Insensitive to original 1: first floor; 2: upper floors  ARCHITECTURAL SIGN □ Significant □ Contributing □ Non-Contributing	; 3: roc			ARCHITECTURAL DESCRIPTION  Style: Open park  Date of Construction: NA  Source: NA  Features: Lincoln Park  Folk Victorian Gazebo in center of park built in 1989 copies pavilion at Pottawatomie Park (1892).



ROLL NO. 1

**NEGATIVE NO. 22** 

Lincoln Park Fourth at Main Streets

## Representation in **Existing Surveys:**

- ☐ Federal
- ☐ State
- ☐ County
- ☐ Local

Block No. 5

**Building No. 1** 

**SURVEY DATE:** 

**MAY 1994** 




# ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

### **CONTINUATION SHEET NO: 1**



ROLL NO. 17

**NEGATIVE NO. 2** 

Lincoln Park Fourth at Main Streets

Remarks:

Block No. 5

**Building No. 1** 

Address:

Remarks:

ROLL NO.

**NEGATIVE NO.** 

Block No.

Building No.