

ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY				BUILDING CONDITION
	1	2	3	☐ Excellent: Well-maintained
☐ Unaltered				☐ Good: Minor maintenance needed
	\boxtimes			☐ Fair: Major repairs needed
☐ Major Alteration				☐ Poor: Deteriorated
□ Additions Sensitive to original Insensitive to original 1: first floor; 2: upper floors; ARCHITECTURAL SIGN □ Significant □ Contributing □ Non-Contributing	3: roc			ARCHITECTURAL DESCRIPTION Style: Gothic Revival Date of Construction: 1925 Source: A Field Gulde to American Houses Features: Church. Gable roof with corner tower. Gable roof entry. Formerly the German Lutheran Church. Rock faced block foundation.



ROLL NO. 8

NEGATIVE NO. 11

315 East Walnut Avenue

Representation in **Existing Surveys:**

- ☐ Federal
- ☐ State
- ☐ County
- ☐ Local

Block No. 54

Building No. 2

SURVEY DATE:

MAY 1994




ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

CONTINUATION SHEET NO: 1



NEGATIVE NO. 12

Address:

315 East Walnut Avenue

Remarks:

East Elevation.

Block No. 54 **Building No. 2**



ROLL NO.

NEGATIVE NO.

Address:

315 Walnut Ave.

Remarks:

Photo taken 8/21

Block No.

Building No.



ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

DIXON ASSOCIATES / ARCHITECTS

CONTINUATION SHEET NO: 1



ROLL NO.

NEGATIVE NO.

Address:

315 WalnutAve.

Remarks:

East Elevation

Photo taken 8/21

Block No.

Building No.

Address:

Remarks:

ROLL NO.

NEGATIVE NO.

Block No.

Building No.

REF. NO. 275