

## ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY				BUILDING CONDITION
	1	2	3	☐ Excellent: Well-maintained
☐ Unaltered				☐ Good: Minor maintenance needed
☐ Minor Alteration				☐ Fair: Major repairs needed
☐ Major Alteration	$\boxtimes$			☐ Poor: Deteriorated
□ Additions □ □ □   Sensitive to original □ □ □ □ □   Insensitive to original □ □ □ □ 1: first floor; 2: upper floors; 3: roof/cornice    ARCHITECTURAL SIGNIFICANCE  □ Significant □ Contributing □ Non-Contributing				ARCHITECTURAL DESCRIPTION  Style: Commercial Vernacular  Date of Construction: 1880-1910  Source: Field Observation  Features:  Two story, greatly modified structure. Synthetic siding at first floor, lannon stone cladding at second floor. Large picture windows at second floor.



**ROLL NO. 13** 

**NEGATIVE NO. 25** 

## Address:

12-14 North 1st Avenue

## Representation in Existing Surveys:

- ☐ Federal
- ☐ State
- ☐ County
- ☐ Local

Block No. 41

**Building No. 11** 

**SURVEY DATE:** 

**MAY 1994**