


ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY				BUILDING CONDITION
	1	2	3	☐ Excellent: Well-maintained
☐ Unaltered				☐ Good: Minor maintenance needed
☐ Minor Alteration	\boxtimes			☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐
☐ Major Alteration				☐ Poor: Deteriorated
 ✓ Additions Sensitive to original Insensitive to original first floor; 2: upper floors; ARCHITECTURAL SIGN 	☐ 3: roo			ARCHITECTURAL DESCRIPTION Style: National style Date of Construction: 1854 Source: St. Charles Historical Museum Features: Cross gable two story wood frame house with front gable porch at entry. Six over six windows at second floor, one
☐ Significant ☐ Contributing	IFIC	ANC	L	over one at first floor. Bay window at first floor of north section.
□ Non-Contributing				,





ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

CONTINUATION SHEET NO: 1



ROLL NO. 6

NEGATIVE NO. 12

Address:

18 South 3rd Avenue

Remarks:

West Elevation.

Block No. 49

Building No. 6



ROLL NO. 16

NEGATIVE NO. 22

Address:

18 South 3rd Avenue

Remarks:

Garage.

Block No. 49

Building No. 6




ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

CONTINUATION SHEET NO: 2



Address:

18 South 3rd Avenue

Remarks:

West Elevation.

ROLL NO. 16

NEGATIVE NO. 21

Block No. 49

Building No. 6

Address:

Remarks:

ROLL NO.

NEGATIVE NO.

Block No.

Building No.