



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 17 North 5th Street

ROLL-IMAGE # 3435 - 19

CD-IMAGE # 4369 - 19



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Prairie 4 square

Exterior Walls (Current): Aluminum

Architectural Features: _____

Exterior Walls (Original): Clapboard

Date of Construction: 1920

Foundation: Textured CMU

Source: Township Assessor's Office

Roof Type/Material: Hipped/Asphalt Shingle

Overall Plan Configuration: 4 square

Window Material/Type: Aluminum/Dbl Hung

ARCHITECTURAL FEATURES: The eaves of the roof are narrow and ungracious for the scale of the roof and home. A 2 – story bay on the south side articulates the mass of the walls and the roofline. The hipped roof dormer centered on the front of the house is another distinguishing feature.

ALTERATIONS: The front porch has been closed in. The windows of the porch do not currently match the rest of the house as the proportions of the openings do not match nor do the muntin patterns. The porch foundation is skirted with a wooden lattice while the deck is accessed by a CIP concrete stoop and a wrought iron railing.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT: _____

Source _____

BUILDER: _____

Source _____

ASSOCIATED EVENTS, PEOPLE & DATES: _____

Source _____

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL: _____

STATE: _____

COUNTY: _____

LOCAL: _____



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 21 North 5th Street

ROLL-IMAGE # 3435 - 20

CD-IMAGE # 4369 - 20



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Prairie 4 square</u>	Exterior Walls (Current):	<u>Stucco/Clapboard</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Stucco/Clapboard</u>
Date of Construction:	<u></u>	Foundation:	<u>Stucco over masonry</u>
Source:	<u></u>	Roof Type/Material:	<u>Hipped/Asphalt Shingle</u>
Overall Plan Configuration:	<u>4 square</u>	Window Material/Type:	<u>Wd trimmed/Alum/Dbf Hung</u>

ARCHITECTURAL FEATURES: The broad eaves and the horizontal trim dividing the ground floor and the second floor are characteristic of the style. Stucco covers the entire house while broad clapboards cover the porch. Columns that start at grade level support the hipped roof of the porch. The bottoms of the porch edge beams are subtly sloped creating an arched effect. The front stoop was rebuilt.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

21 North 5th Street - Continuation Sheet

ALTERATIONS: The eaves are boxed in aluminum. A porch and deck are additions that are not sympathetic with the original architectural style. The front stoop is CIP concrete with a wrought iron railing. The original stucco covering the front porch has been replaced with clapboard.

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

The Colonial Ice Cream Anderson family is associated with this house. Simon Anderson had the house built in 1909 for his wife Lily. Simon founded the family business in 1901. The house featured one of the first three car garages in town.

Source

Current owner (Chad & Michele Daley)/Tom Anderson

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL:

STATE:

COUNTY:

LOCAL:

YES



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 115 North 5th Street

ROLL-IMAGE # 3435 - 21

CD-IMAGE # 4369 - 21



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Victorian/Queen Anne</u>	Exterior Walls (Current):	<u>Composition shingle</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard</u>
Date of Construction:	<u>1900</u>	Foundation:	<u>Parged masonry</u>
Source:	<u>Township Assessor's Office</u>	Roof Type/Material:	<u>Cross gable/Asphalt shingle</u>
Overall Plan Configuration:	<u>Simple rectangle</u>	Window Material/Type:	<u>Wd trimmed/Alum/Dbl Hung</u>

ARCHITECTURAL FEATURES: It appears that the front porch was remodeled at some time, as the detailing does not match the side porch. The side porch still retains the original spindle work and turned columns while a single square column supports the front porch and the rail is comprised of square balusters. The front stairs are constructed of wood and has a wrought iron handrail.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

115 North 5th Street - Continuation Sheet

ALTERATIONS: The original Victorian era details were removed when the house was resided with the composition shingle siding. The eaves are open and are sheathed with aluminum. The front entry doors are aluminum.

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL: YES



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 202 North 5th Street

ROLL-IMAGE # 3432 - 8

CD-IMAGE # 4367 - 8



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Victorian/Queen Anne</u>	Exterior Walls (Current):	<u>Aluminum</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard</u>
Date of Construction:	<u>1910</u>	Foundation:	<u>Stone</u>
Source:	<u>Township Assessor's Office</u>	Roof Type/Material:	<u>Hipped w/ lower cross gables/ Asphalt Shingle</u>
Overall Plan Configuration:	<u>Simple w/ additions</u>	Window Material/Type:	<u>Wd Trim/Alum/Dbf Hung</u>

ARCHITECTURAL FEATURES: The spindle-work detailing on the porch is the most striking feature of the house. The turned columns that support the porch roof appear to be thin in proportion to their function. The porch end is gracefully curved as it returns to the main mass of the house. The front gable has cutaway corners on the ground floor somewhat concealed by the roof of the porch. There is also a leaded glass transom on the ground floor bay on the porch. The eaves re open. The stone foundation is an important feature contributing to the historic character of the facades.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

202 North 5th Street - Continuation Sheet

ALTERATIONS: A lot of the historic details were lost when the house was re-sided with aluminum. The imbrication that would have been located in the gable ends was concealed/removed. The eaves are covered with aluminum. A two story open deck was added to the rear of the house that features no Queen Anne detailing and is therefore not compatible. The spindle work detailing appears to have been added as the proportions don't seem appropriate.

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 203 North 5th Street

ROLL-IMAGE # 3432 - 7

CD-IMAGE # 4367 - 7



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Victorian/Queen Anne</u>	Exterior Walls (Current):	<u>Clapboard</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard</u>
Date of Construction:	<u>1910</u>	Foundation:	<u>Stone-orig/Parged CMU-add.</u>
Source:	<u>Township Assessor's Office</u>	Roof Type/Material:	<u>Hipped w/ lower cross gables/ Asphalt shingle</u>
Overall Plan Configuration:	<u>Simple w/ additions</u>	Window Material/Type:	<u>Wd trim/Alum Dbl Hung/ Some removable storms remain</u>

ARCHITECTURAL FEATURES: There is a noticeable absence of imbrication in the gable ends – which could mean that the house was re-sided. The heads of the window trim appear to have been removed as brackets that would have supported them remain. Original spindle-work details remain on a small entry porch asymmetrically placed on the front elevation. Fish-scale shingles were used on the small roof covering the ground floor window of the front gable end. This window project slightly and is supported by two wooden brackets. The stone foundation contributes to the historic character of the house. The eaves are open and are sheathed in wood.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

203 North 5th Street - Continuation Sheet

ALTERATIONS: A 1 ½ story addition was made to the rear of the house that maintains the character of the original style. The siding appears to have been replaced stripping some of the details of the original house.

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL: YES



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 19 South Fifth Street

ROLL-IMAGE # 102 - 2

CD-IMAGE # 4405 - 17



ARCHITECTURAL SIGNIFICANCE

- **Significant**
- ☐ Contributing
- ☐ Non-Contributing
- **Designated on the National Historic Register**

BUILDING CONDITION

- ☐ Excellent
- **Good**
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Greek Revival

Architectural Features: _____

Date of Construction: 1859

Source: Heritage Center

Overall Plan Configuration: L Shape

Exterior Walls (Current): Wood clapboard / wood frame

Exterior Walls (Original): Wood clapboard / wood frame

Foundation: Stone

Roof Type/Material: Gabled / asphalt shingles

Window Material/Type: Wood / Double hung

ARCHITECTURAL FEATURES: Features a large 2 story gabled portico supported by stylized Greek Doric columns. There is a 2nd story balcony supported by the portico columns. The portico is designed in the Greek temple form. The house is sited on a hill, also typical of Greek temple planning. The window surrounds exhibit typically simple Greek detailing. The house is sided with narrow wood clapboards with a 5" exposure.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

19 South Fifth Street - Continuation Sheet

ALTERATIONS: There was a second floor section added over the dining room and parlor. The conservatory off the dining room and the closet off the first floor SE bedroom are also later additions. John A. Brown, who purchased the property in 1885, added French doors to the second floor porch during an extensive interior remodeling.

HISTORIC INFORMATION:

ARCHITECT: Unknown
Source

BUILDER: Unknown
Source

ASSOCIATED EVENTS, PEOPLE & DATES: Dr. James K. Lewis, the first mayor of St. Charles, built the house in 1859. Dr. Lewis served as mayor from 1875 –1883. He practiced medicine, after his tenure as mayor, until 1892. He also dealt in real estate. He died in 1907.

Source Heritage Center

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL: YES
STATE: YES
COUNTY:
LOCAL: YES



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 117 South 5th Street

ROLL-IMAGE # 3435 - 27

CD-IMAGE # 4369 - 27



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Eclectic

Architectural Features: _____

Date of Construction: 1930

Source: Township Assessor's Office

Overall Plan Configuration: Compound w/ Additions

Exterior Walls (Current): Brick/Alum

Exterior Walls (Original): Clapboard

Foundation: Concrete

Roof Type/Material: Cross gable/Asphalt Shingle

Window Material/Type: Wd trim/Alum/Dbf Hung

ARCHITECTURAL FEATURES: This is currently a multi-family residence with an address of 500 W. Indiana on the side entrance. The 1 ½ story portico over the 5th Street entrance is the dominant architectural feature. Here large disproportionate square columns support a gabled roof. The gable end is cut out in an almost Post Modern manner expressing no particular stylistic reference. An elaborated surround adds emphasis and interest to what appears to be the main entry. The overall impression is Colonial revival but a lack of appropriate details precludes classification as such.

ALTERATIONS: The original house was a modest structure that is now completely hidden by numerous additions and modifications.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT: _____

Source _____

BUILDER: _____

Source _____

ASSOCIATED EVENTS, PEOPLE & DATES: _____

Source _____

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL: _____

STATE: _____

COUNTY: _____

LOCAL: _____



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 207 South 5th Street

ROLL-IMAGE # 3178 - 1

CD-IMAGE # 032D - 1



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing (Orig.)
- ☒ Non-Contributing (Current)
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Eclectic – Modified</u>	Exterior Walls (Current):	<u>Clapboard</u>
	<u>Cape Cod</u>		
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard</u>
	<u></u>		
Date of Construction:	<u>1910</u>	Foundation:	<u>Concrete</u>
Source:	<u>Township Assessor's Office</u>	Roof Type/Material:	<u>Cross gable</u>
	<u></u>		
Overall Plan Configuration:	<u>Simple - L</u>	Window Material/Type:	<u>Wood/Dbf Hung</u>

ARCHITECTURAL FEATURES: This house possessed a diminutive scale adding to its charming street presence. The porch was covered with the continuation of the main roof tucked in beneath the eave of the front gable. The entrance was not emphasized as it was tucked into the corner of the porch. The doorway did not have special trim. The two windows placed in the front gable had an extra crown molding that the other windows did not have.

ALTERATIONS: The original house was totally transformed from what is pictured here. A substantial addition has been made to the north and west sides of the original structure. The original house has been completely remodeled.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 213 South 5th Street

ROLL-IMAGE # 70549 - 36

CD-IMAGE # 0601 - 36



ARCHITECTURAL SIGNIFICANCE

- Significant
- ☐ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- Excellent
- ☐ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Romantic/gothic revival</u>	Exterior Walls (Current):	<u>Clapboard</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard</u>
Date of Construction:	<u>1900</u>	Foundation:	<u></u>
Source:	<u>Township Assessor's Office</u>	Roof Type/Material:	<u>Cross gable/Asphalt shingle</u>
Overall Plan Configuration:	<u>Simple w/irregularities</u>	Window Material/Type:	<u>Wd/dbl. hung</u>

ARCHITECTURAL FEATURES: Steeply pitched cross gabled roofs where the smaller front gable is even more steeply pitched than the other roofs. This smaller front gable and the side gable are clipped. Decorated barge boards run along the rakes of the gables. All of the walls extend into the gable thereby exaggerating the height of the façade which is typical of the style. The window surrounds are detailed with an elaborate head trim. The porch supports are square columns that feature flattened arches.

ALTERATIONS:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Secondary Structure

ADDRESS 213 South 5th Street

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT: Unknown
Source _____

BUILDER: Unknown
Source _____

ASSOCIATED EVENTS, PEOPLE & DATES: This was the home of James Perkins Furnald who was born is 1813. Mr. Furnald was a well-known tailor who came to St. Charles in 1845. He was also a lieutenant in captain Bowman's Company of Light Guards.
Source St. Charles of Illinois by David A. Badger

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL: _____
STATE: YES
COUNTY: _____
LOCAL: YES



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 221 South 5th Street

ROLL-IMAGE # 3435 - 28

CD-IMAGE # 4369 - 28



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☒ Excellent
- ☐ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: <u>Victorian – Queen Anne</u>	Exterior Walls (Current): <u>Vinyl drop style siding</u>
Architectural Features: <u></u>	Exterior Walls (Original): <u>Clapboard</u>
Date of Construction: <u>1900</u>	Foundation: <u>Parged masonry</u>
Source: <u>Township Assessor's Office</u>	Roof Type/Material: <u>Front gable/Asphalt shingle</u>
Overall Plan Configuration: <u>Simple rectangle w/ Addition</u>	Window Material/Type: <u>Wd trimmed/Alum/Dbl Hung</u>

ARCHITECTURAL FEATURES: An elevated site contributes to the impression of a large-scale street presence. The 12:12 roof slope adds vertical emphasis. Fish-scale shingles decorate the front gable end of the façade flowing in a fluid manner over the window heads to provide some protection from the elements. The flare at the third story window is a gentle curve. The heads of the second story windows of the front elevation are covered with a small roof that is the continuation of the fish-scale shingles sloping gently out from the main plane of the gable end. A relatively broad frieze board trim was used along the rake of the front gable.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

221 South 5th Street - Continuation Sheet

ALTERATIONS: The house was re-sided with a drop styled vinyl siding. The front porch was closed in with windows that are banded together – unlike any other opening in the house. A small one story addition was made to the rear of the house. The front stoop was remodeled using an attractive mix of brick risers and stone treads with wrought iron railings.

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 315 South 5th Street

ROLL-IMAGE # 70549 - 35

CD-IMAGE # 0601 - 35



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☐ Good
- ☒ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Victorian-Folk Victorian

Architectural Features: _____

Date of Construction: 1860

Source: Township Assessor's Office

Overall Plan Configuration: Compound-Cross

Exterior Walls (Current): Aluminum

Exterior Walls (Original): Clapboard

Foundation: Parged masonry

Roof Type/Material: Cross gable/Asphalt Shingle

Window Material/Type: Wood/DbI Hung/
Removable storms

ARCHITECTURAL FEATURES: The front gable is the dominant architectural element of the façade. A small-hipped roof supported by ornate wooden brackets tops a one-story bay window on the ground floor of the front gable. Wooden brackets support the overhang and patterned vergeboards decorate the peak of the front gable. Carved wooden brackets support a small-hipped roof over the entrance located off center to the left of the front gable. Modest pediment forms are typically used over the window heads. The front stoop is constructed with native stone and appears to be original construction.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

315 South 5th Street - Continuation Sheet

ALTERATIONS: A small-screened porch was added to the rear of the house. The front storm door is aluminum.

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 318 South 5th Street

ROLL-IMAGE # 3435 - 29

CD-IMAGE # 4369 - 29



ARCHITECTURAL SIGNIFICANCE

- Significant
- ☐ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Victorian/Queen Anne</u>	Exterior Walls (Current):	<u>Clapboard</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard</u>
Date of Construction:	<u>1915</u>	Foundation:	<u>Parged stone</u>
Source:	<u>Township Assessor's Office</u>	Roof Type/Material:	<u>Cross gable/Asphalt shingle</u>
Overall Plan Configuration:	<u>Compound -Cross</u>	Window Material/Type:	<u>Wd trimmed/Alum/Dbf Hung</u>

ARCHITECTURAL FEATURES: The roof slope is very steep. It is approximately 16:12 or greater. Fish scale shingles in the gable ends top the two story bays. Large wooden brackets support the deep overhangs here where the corners are cut back and the eaves continue. The eaves are open and are sheathed with smooth wood sheathing. Turned wooden columns support the hipped roof over the front entry. Spindle-work decorates the eave of the porch while the balusters of the railings are square. The windows are trimmed with crown moldings at the head visually supported by bulls-eye "brackets".

ALTERATIONS: The porch railing has been replaced. The entry has an aluminum storm door. All of the original wood windows have been replaced with aluminum.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 321 South 5th Street

ROLL-IMAGE # 3436 - 12

CD-IMAGE # 4189 - 12



ARCHITECTURAL SIGNIFICANCE

- ☒ Significant
☐ Contributing
☐ Non-Contributing
☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
☒ Good
☐ Fair
☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Gothic Revival</u>	Exterior Walls (Current):	<u>Clapboard</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard</u>
Date of Construction:	<u>1890</u>	Foundation:	<u>Concrete</u>
Source:	<u>Township Assessor's Office</u>	Roof Type/Material:	<u>Cross gable/Asphalt shingle</u>
Overall Plan Configuration:	<u>Compound – Cross w/adds.</u>	Window Material/Type:	<u>Wd/DbI Hung/Rmvble.storms</u>

ARCHITECTURAL FEATURES: The massing of this house similar to the house next door @ 315 South 5th. The plan is mirrored and the system of details differs. This house features a consistent Gothic detail vocabulary. The paired windows on the second floor of the front gable have pointed tops as do the second floor windows on the north and south gable ends. Shaped wooden trim is consistently used around all of the window and door openings. The window head trim is sloped when the sashes are squared off. The front gable end is topped with decorative vergeboards, a broad frieze board, and also features a one-story bay window that has a hipped roof supported by wooden brackets. The front window of the bay has a leaded glass transom. Round Doric columns support the hipped roof of the small porch located over the front door.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

321 South 5th Street - Continuation Sheet

ALTERATIONS: There have been two additions to the rear of the house that are relatively sympathetic with the original style.

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 407 South 5th Street

ROLL-IMAGE # 3436 - 13

CD-IMAGE # 4189 - 13



ARCHITECTURAL SIGNIFICANCE

- **Significant**
- ☐ Contributing
 - ☐ Non-Contributing
 - ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- **Excellent**
- ☐ Good
 - ☐ Fair
 - ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Prairie Style
Architectural Features: _____
Date of Construction: 1909
Source: Township Assessor's Office
Overall Plan Configuration: Rectangular

Exterior Walls (Current): Textured Masonry
Exterior Walls (Original): Textured Masonry
Foundation: Masonry
Roof Type/Material: Hipped/Asphalt shingle
Window Material/Type: Wd trimmed/Alum/Dbf Hung

ARCHITECTURAL FEATURES: Appears to have used concrete masonry units intended to simulate stone. This was popular in the early part of this century and was thought to be a novel new building material. The roof has symmetrically planned hipped dormers with broad overhangs. The main part of the roof also has the broad overhangs that are emphasized by the broad frieze board detailing beneath the eave. Massive stone piers support the carport and the porch. The stringcourses of masonry located at the 2nd floor line that tie into the carport roof detailing further emphasize the horizontality of the façade. A screened porch located next to the carport is integrated into the main mass of the house.

ALTERATIONS: Aluminum windows replaced the original wooden units.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

407 South 5th Street - Continuation Sheet

Secondary Structure

ADDRESS 407 South 5th Street

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT: Unknown
Source _____

BUILDER: Unknown
Source _____

ASSOCIATED EVENTS, PEOPLE & DATES: This was the home of William D. & Dottie Lillibridge. William was a prominent merchant in town and owned an interest in the St. Charles Lumber Co. He also was president of a hammock company and the Lillibridge Manufacturing Company.
Source St. Charles of Illinois by David A. Badger

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL: _____
STATE: YES
COUNTY: _____
LOCAL: YES. Local Landmark Designation



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 420 South 5th Street

ROLL-IMAGE # 3434 - 25

CD-IMAGE # 4368 - 25



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Modern Ranch

Architectural Features: _____

Date of Construction: 1964

Source: Township Assessor's Office

Overall Plan Configuration: Simple Rectangle

Exterior Walls (Current): Composition Board

Exterior Walls (Original): Composition Board

Foundation: Concrete

Roof Type/Material: Hipped/Asphalt shingle

Window Material/Type: Wd trimmed/Alum/DbI Hung

ARCHITECTURAL FEATURES: The massing is low and horizontal. The eaves are continuous further emphasizing the horizontal. A large two car garage door and the picture window are the dominant architectural features of the front elevation.

ALTERATIONS:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 421 South 5th Street

ROLL-IMAGE # 70549 - 32

CD-IMAGE # 0601 - 32



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Prairie – Orig.

Architectural Features: _____

Date of Construction: 1925

Source: Township Assessor's Office

Overall Plan Configuration: Simple Rectangle w/ addition

Exterior Walls (Current): Aluminum

Exterior Walls (Original): Clapboard

Foundation: Concrete

Roof Type/Material: Hipped/Asphalt shingle

Window Material/Type: Wd trimmed/Alum/DbI Hung

ARCHITECTURAL FEATURES: The broad boxed eaves emphasize the horizontality of the façade. The main mass of the façade is symmetrical. An eyebrow dormer is placed on the central axis as is the entry porch. Paired windows on the ground floor are aligned with single windows on the second floor.

ALTERATIONS: Aluminum siding replaced the original clapboards. The soffits are boxed with aluminum, the windows and front storm door are aluminum. A small gabled roof shelters the centrally placed front door. This element was remodeled from the original, as it is not in character with the overall design and details. The stoop is CIP concrete with wrought iron railings.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 427 South 5th Street

ROLL-IMAGE # 70549 - 33

CD-IMAGE # 0601 - 33



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Victorian – Shingle Style

Architectural Features: _____

Date of Construction: 1900

Source: Township Assessor's Office

Overall Plan Configuration: Simple w/ adds

Exterior Walls (Current): Wd shingles/Clapboard

Exterior Walls (Original): Wd shingles/Clapboard

Foundation: Stone w/ beaded joints

Roof Type/Material: Cross gable/Asphalt shingle

Window Material/Type: Wd trimmed/Alum/Dbf Hung

ARCHITECTURAL FEATURES: Wood shingles were used on the second floor while clapboards were used on the ground floor. There are no corner boards. The gable ends feature projected pediments with circular cutouts. Large wooden brackets support the projections. The front porch is covered by a continuation of the main roof. A turned column supports the roof, which is detailed with spindle-work, and the porch railings are supported by turned balusters. A gracefully curving pair of railings guide the user up the front steps to what appears to be the original wooden front door. The surround is trimmed with pilasters at the jambs and crown moldings at the head.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

427 South 5th Street - Continuation Sheet

ALTERATIONS: Two substantial additions have been made to the rear of the house. Both additions have shed roofs that are out of character with the style of the original house. One addition is 1 story and the other is 2-story. The original windows have been replaced with aluminum inserts.

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL:

STATE:

COUNTY:

LOCAL: YES



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 500 South 5th Street

ROLL-IMAGE # 3434 - 24

CD-IMAGE # 4368 - 24



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☐ Good
- ☒ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Bungalow (Craftsman)

Exterior Walls (Current): Clapboard

Architectural Features: _____

Exterior Walls (Original): Clapboard

Date of Construction: 1930

Foundation: Concrete

Source: Township Assessor's Office

Roof Type/Material: Front Gable/Asphalt shingle

Overall Plan Configuration: Simple rectangle

Window Material/Type: Wd trimmed/Alum/Dbf Hung

ARCHITECTURAL FEATURES: This house is sparingly detailed. There are few details to note even though the elevations appear to be substantially original. The front porch columns are square and start at the top of the porch rail. The triple window centered over the front door is reminiscent of a Palladian styled window without the finesse and detail. Corner boards were installed to trim the siding.

ALTERATIONS: The front porch has been closed in and the front door was moved out to the front of the porch.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT: _____

Source _____

BUILDER: _____

Source _____

ASSOCIATED EVENTS, PEOPLE & DATES: _____

Source _____

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL: _____

STATE: _____

COUNTY: _____

LOCAL: _____



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 503 South 5th Street

ROLL-IMAGE # 70549 - 34

CD-IMAGE # 0601 - 34



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Craftsman Bungalow

Exterior Walls (Current): Clapboard

Architectural Features: _____

Exterior Walls (Original): Clapboard

Date of Construction: 1920

Foundation: Concrete

Source: Township Assessor's Office

Roof Type/Material: Side Gable/Asphalt shingle

Overall Plan Configuration: Simple rectangle

Window Material/Type: Wd /Dbl Hung

ARCHITECTURAL FEATURES: This house is typically detailed in keeping with the style. Broad overhangs, large wooden brackets supporting the roof, and exposed rafter tails are notable typical details. The elevations appear to be substantially original. The front porch columns are square and start at grade. Two column pedestals flank the front steps and the porch railings are wood detailed in the Craftsman tradition. Pointed arched openings are an interesting design detail used on the porch. The front door is centered and the surround is simply trimmed without detail emphasis. The triple window in the gabled dormer is centered over the front door and features a 4:1 muntin pattern. No corner boards were installed to trim the siding.

ALTERATIONS:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT: _____

Source _____

BUILDER: _____

Source _____

ASSOCIATED EVENTS, PEOPLE & DATES: _____

Source _____

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL: _____

STATE: _____

COUNTY: _____

LOCAL: _____



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 506 South 5th Street

ROLL-IMAGE # 3434 - 23

CD-IMAGE # 4368 - 23



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☐ Good
- ☒ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: <u>Craftsman Bungalow</u>	Exterior Walls (Current): <u>Brick</u>
Architectural Features: _____	Exterior Walls (Original): <u>Brick</u>
Date of Construction: <u>1930</u>	Foundation: <u>Concrete</u>
Source: <u>Township Assessor's Office</u>	Roof Type/Material: <u>Side Gable/Asphalt shingle</u>
Overall Plan Configuration: <u>Simple rectangle</u>	Window Material/Type: <u>Wd /Dbl Hung/Rmvbl Storms</u>

ARCHITECTURAL FEATURES: This house is typically detailed in keeping with the style. Broad overhangs, large wooden brackets supporting the roof, and exposed rafter tails are notable typical details. The front porch columns are square and start at the top of the porch rail. The porch railings are brick and are capped with stone. Arched openings are an interesting design detail used on the porch. The front door is not centered and the surround is simply trimmed without detail emphasis. The triple window in the gabled dormer is not centered over the front door and features a 6:1 muntin pattern.

ALTERATIONS: Simulated brick patterned asphalt sheeting was used in some portions of the upper story.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT: _____

Source _____

BUILDER: _____

Source _____

ASSOCIATED EVENTS, PEOPLE & DATES: _____

Source _____

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL: _____

STATE: _____

COUNTY: _____

LOCAL: _____



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 512 South 5th Street

ROLL-IMAGE # 3434 - 22

CD-IMAGE # 4368 - 22



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Bungalow – Orig.</u>	Exterior Walls (Current):	<u>Composite Siding</u>
	<u>4 Square - Current</u>		
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard</u>
Date of Construction:	<u>1930</u>	Foundation:	<u>Concrete</u>
Source:	<u>Township Assessor's Office</u>	Roof Type/Material:	<u>Hipped/Asphalt Shingle</u>
Overall Plan Configuration:	<u>Simple rectangle</u>	Window Material/Type:	<u>Wd trim/Alum/Dbf Hung</u>

ARCHITECTURAL FEATURES: The original house was a simple bungalow lacking notable details that would classify it as a Craftsman bungalow. The eaves were open. The porch was closed in and its supporting columns began at grade.

ALTERATIONS: A second story addition has been made to this house since the above photograph was taken. The house has been re-sided.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT: _____

Source _____

BUILDER: _____

Source _____

ASSOCIATED EVENTS, PEOPLE & DATES: _____

Source _____

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL: _____

STATE: _____

COUNTY: _____

LOCAL: _____



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 618 South 5th Street

ROLL-IMAGE # 70551 - 1

CD-IMAGE # 0601 - 73



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Colonial revival - Garrison</u>	Exterior Walls (Current):	<u>Aluminum</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard</u>
Date of Construction:	<u>1947</u>	Foundation:	<u>Concrete</u>
Source:	<u>Township Assessor's Office</u>	Roof Type/Material:	<u>Side Gable/Asphalt shingle</u>
Overall Plan Configuration:	<u>Simple rectangle w/ adds</u>	Window Material/Type:	<u>Wd trim/Alum /Dbl Hung</u>

ARCHITECTURAL FEATURES: An overhang of the second floor beyond the first floor distinguishes this as the Garrison subtype. Fluted pilasters and a tall header featuring crown moldings emphasize the front entry. The large picture window on the first floor is a deviation from the style.

ALTERATIONS: The garage and the second story living area above it was added to the north side of the house. A one story flat roofed addition and a one story shed roof addition were made to the rear of the house. None of these additions are sympathetic with the original style. The openings are too large and the materials are modern.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 619 South 5th Street

ROLL-IMAGE # 70552 - 29

CD-IMAGE # 0602 - 29



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Prairie 4 square

Exterior Walls (Current): Aluminum

Architectural Features: _____

Exterior Walls (Original): Clapboard

Date of Construction: 1924

Foundation: Concrete

Source: Township Assessor's Office

Roof Type/Material: Hipped/Asphalt shingle

Overall Plan Configuration: 4 square

Window Material/Type: Wd trim/alum/DbI Hung

ARCHITECTURAL FEATURES: Broad closed eaves under a hipped roof and the symmetrical front façade help distinguish this as a Prairie styled design.

ALTERATIONS: The 1 story hipped roof addition to the south side of the house is not sympathetic with the original style. It is not tied with any discernible horizontal detail lines to the main part of the house. The window proportions are also off. The front porch has been closed off concealing the structure and any of the decorative detailing that might have existed. Low brick walls and wrought iron railings flank the front stoop. The window in front dormer has been removed and replaced with a louver.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 624 South 5th Street

ROLL-IMAGE # 70551 - 2

CD-IMAGE # 0601 - 74



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Modern ranch</u>	Exterior Walls (Current):	<u>Clapboard</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard</u>
Date of Construction:	<u>1950</u>	Foundation:	<u>Concrete</u>
Source:	<u>Township Assessor's Office</u>	Roof Type/Material:	<u>Side gable w/ lower cross Gables/Asphalt shingle</u>
Overall Plan Configuration:	<u>Simple - Rectangle</u>	Window Material/Type:	<u>Wd trim/Alum/Dbf Hung</u>

ARCHITECTURAL FEATURES: Reverse board and batten siding separate the two front gables. The gable ends feature broken pediments. There is a small bow window placed in the center part of the front elevation. The façade is relatively symmetrical.

ALTERATIONS: The lattice screen and its associated fiberglass canopy were added at the entry.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 625 South 5th Street

ROLL-IMAGE # 70552 - 28

CD-IMAGE # 0602 - 28



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Prairie Bungalow

Architectural Features: _____

Date of Construction: 1925

Source: Township Assessor's Office

Overall Plan Configuration: Simple rectangle

Exterior Walls (Current): Brick

Exterior Walls (Original): Brick

Foundation: Concrete

Roof Type/Material: Hipped/Asphalt shingle

Window Material/Type: Wd/Dbt Hung/Rem. Storms
Alum inserts @ dormers

ARCHITECTURAL FEATURES: There appears to be an overall horizontal emphasis. The roof ridge continues forward to form the ridge of the front dormer. The ridge of the south-facing dormer is also placed at the same elevation as the main roof. The eaves are closed and wide. Most of the windows are grouped in twos and threes adding further emphasis to the horizontal. A small bay window is placed directly beneath the south dormer. The front stoop is CIP concrete and has wrought iron railings.

ALTERATIONS: The front porch has been closed in and has an aluminum storm door.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 629 South 5th Street

ROLL-IMAGE # 70552 - 27

CD-IMAGE # 0602 - 27



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Craftsman Bungalow

Architectural Features: _____

Date of Construction: 1925

Source: Township Assessor's Office

Overall Plan Configuration: Simple - Rectangle

Exterior Walls (Current): Aluminum

Exterior Walls (Original): Clapboard

Foundation: Concrete

Roof Type/Material: Side gable/Asphalt shingle

Window Material/Type: Alum/Dbf Hung

ARCHITECTURAL FEATURES: The first floor appears to be taller than is typical for the style. Note the extra height above the windows w/ respect to the eaves. A large shed dormer centered over the closed in front porch are the dominant elements of the front elevation. The side elevations feature the original wooden brackets that support the wide roof overhangs.

ALTERATIONS: A one-story shed roofed addition was made to the rear. Many of the original details were lost or concealed when the house was re-sided in aluminum. No exposed rafter tails are visible as one would expect and all of the original porch detailing is hidden.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 700 South 5th Street

ROLL-IMAGE # 70551 - 3

CD-IMAGE # 0601 - 75



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Eclectic - Tudor

Architectural Features: _____

Date of Construction: 1929

Source: Township Assessor's Office

Overall Plan Configuration: Compound - Cross

Exterior Walls (Current): Brick

Exterior Walls (Original): Brick

Foundation: Concrete

Roof Type/Material: Side gable w/ lower cross
Gable/Asphalt shingle

Window Material/Type: Wd trim/Alum/Dbf Hung

ARCHITECTURAL FEATURES: A steeply sloped (16:12est.) roof of the front gable covers the main entry. A keystone is placed over an arched topped front door. Simply detailed wooden brackets support the roof overhang here. The large brick chimney located next to the front gable adds an element of charming cottage like scale to the front façade. The upper sashes of the windows feature a diagonal muntin pattern and leaded glass. The roof shingles appear to simulate wood shingles.

ALTERATIONS:



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 701 South 5th Street

ROLL-IMAGE # 70552 - 26

CD-IMAGE # 0602 - 26



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Bungalow

Architectural Features: _____

Date of Construction: 1925

Source: Township Assessor's Office

Overall Plan Configuration: Simple - Rectangle

Exterior Walls (Current): Brick

Exterior Walls (Original): Brick

Foundation: Concrete

Roof Type/Material: Front gable/Asphalt shingle

Window Material/Type: Wd trim/alum/DbI Hung

ARCHITECTURAL FEATURES: The front entry is not centered and features arched brick openings and an unusual roof design. It appears that the roof is a shed design from the view depicted in the photograph. It is in fact a north facing gable intersecting the main roof at an unusual location. All of the gable all feature broken pediments – from the dormers to the main front gable. Many of the windows are grouped together in fours, threes, and twos. The eaves are boxed and are relatively wide.

ALTERATIONS:



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 702 South 5th Street

ROLL-IMAGE # 70551 - 4

CD-IMAGE # 0601 - 76



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Colonial Revival - Dutch

Exterior Walls (Current): Clapboard

Architectural Features:

Exterior Walls (Original): Clapboard

Date of Construction: 1947

Foundation: Concrete

Source: Township Assessor's Office

Roof Type/Material: Side gambrel/Asphalt shingle

Overall Plan Configuration: Simple rectangle w/ adds

Window Material/Type: Wd trim/Alum/DbI Hung

ARCHITECTURAL FEATURES: The entry is not centered on the front elevation. There is no detailed surround at the front door. The roof dormers are small in proportion to the rest of the façade.

ALTERATIONS: The front bay window and the hipped roof over it were added. A one story addition was made to the rear of the house. The storm door is aluminum as are all of the windows.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:

YES



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 707 South 5th Street

ROLL-IMAGE # 70552 - 25

CD-IMAGE # 0602 - 25



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Colonial Revival

Architectural Features:

Date of Construction: 1941

Source: Township Assessor's Office

Overall Plan Configuration: Simple rectangle

Exterior Walls (Current): Aluminum

Exterior Walls (Original): Clapboard

Foundation: Concrete

Roof Type/Material: Side gable/Asphalt shingle

Window Material/Type: Alum/DbI Hung

ARCHITECTURAL FEATURES: This is a three rank design. The façade is symmetrical with the front door centered on the elevation. The entry surround is composed of smooth aluminum pilasters and a tall header with crown molding detailing. There is no roof overhang.

ALTERATIONS: A shed-roofed porch was added to the rear of the house. The wood original siding was replaced with aluminum.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 712 South 5th Street

ROLL-IMAGE # 70551 - 5

CD-IMAGE # 0601 - 77



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☐ Good
- ☒ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	National style bungalow	Exterior Walls (Current):	Aluminum
Architectural Features:		Exterior Walls (Original):	Clapboard
Date of Construction:	1925	Foundation:	Textured CMU
Source:	Township Assessor's Office	Roof Type/Material:	Front gable/Asphalt shingle
Overall Plan Configuration:	Simple rectangle	Window Material/Type:	Wd trim/Alum/Dbf Hung

ARCHITECTURAL FEATURES: The roof pitch is shallow (6:12 est.). There is no decorative detailing. This is a simple and plain house.

ALTERATIONS: The front porch has been closed in. Aluminum siding has replaced the original clapboards. A non-sympathetic garage addition was made to the north side of the house.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT: _____

Source _____

BUILDER: _____

Source _____

ASSOCIATED EVENTS, PEOPLE & DATES: _____

Source _____

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL: _____

STATE: _____

COUNTY: _____

LOCAL: _____



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 713 South 5th Street

ROLL-IMAGE # 70552 - 24

CD-IMAGE # 0602 - 24



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Modern –stylized Colonial

Architectural Features: _____

Date of Construction: 1973

Source: Township Assessor's Office

Overall Plan Configuration: Simple rectangle w/ adds.

Exterior Walls (Current): Aluminum

Exterior Walls (Original): Aluminum

Foundation: Concrete

Roof Type/Material: Side gable/Asphalt shingle

Window Material/Type: Alum/DbI Hung

ARCHITECTURAL FEATURES: The two-car garage and the paired windows are the main design features of the front elevation. The entrance is not emphasized, as it should be in the Colonial Revival styles.

ALTERATIONS:



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 717 South 5th Street

ROLL-IMAGE # 70552 - 23

CD-IMAGE # 0602 - 23



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Prairie 4 square

Architectural Features: _____

Date of Construction: 1925

Source: Township Assessor's Office

Overall Plan Configuration: 4 square

Exterior Walls (Current): Wood shingles @ 2F
Alum @ 1F

Exterior Walls (Original): Wood shingles @ 2F
Clapboard @ 1F

Foundation: Concrete

Roof Type/Material: Hipped/Asphalt shingle

Window Material/Type: Wd trim/Alum/Dbf Hung

ARCHITECTURAL FEATURES: The wide boxed eaves and the change of materials from the first floor to the second floor contribute to the horizontal character of the house. Most of the windows are grouped together which is a design device used often in the Prairie styled houses. The entrance is off center and is emphasized by a curved top canopy that is supported by two heavy wooden brackets. The one story plan projection to the south of the house is in character with the rest of the house. It has a hipped roof and is tied in by the use of materials and the banded windows.

ALTERATIONS: The front steps are CIP concrete with turned balusters – not in character with the style.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 781 South 5th Street

ROLL-IMAGE # 70551 - 6

CD-IMAGE # 0601 - 78



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: <u>National – 1 ½ story</u>	Exterior Walls (Current): <u>Aluminum</u>
Architectural Features: _____	Exterior Walls (Original): <u>Clapboard</u>
Date of Construction: <u>1910</u>	Foundation: <u>Textured CMU</u>
Source: <u>Township Assessor's Office</u>	Roof Type/Material: <u>Front gable/Asphalt shingle</u>
Overall Plan Configuration: <u>Simple rectangle</u>	Window Material/Type: <u>Wd trim/Alum/Dbf Hung</u>

ARCHITECTURAL FEATURES: A full width front porch covered by a hipped roof creates a pleasant entrance transition to the front door. Tapered wooden columns that begin at the porch deck support the porch roof. There is a stained glass transom at the front living room window. The eaves are narrow and are boxed in with aluminum. This is very plain house with no decorative detailing

ALTERATIONS: Aluminum has replaced the all of the original materials.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 720 South 5th Street

ROLL-IMAGE # 70551 - 7

CD-IMAGE # 0601 - 79



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Eclectic - Tudor

Architectural Features: _____

Date of Construction: 1926

Source: Township Assessor's Office

Overall Plan Configuration: Simple rectangle w/adds

Exterior Walls (Current): Aluminum

Exterior Walls (Original): Clapboard

Foundation: Concrete

Roof Type/Material: Cross gable/Asphalt shingle

Window Material/Type: Alum/Dbf Hung

ARCHITECTURAL FEATURES: The steeply sloped roof (16:12 est.) curves at the eaves. The small front porch is covered by the continuation of the main roof. A single square wooden post supports the porch roof. A shed dormer is nestled into the valley of the front and crossing gable. The windows at the 2F and 1F of the front gable are paired and centered atop each other.

ALTERATIONS: A one-story flat roof addition was made to the rear of the house. Aluminum siding and windows have replaced the original wood materials. No original details can be seen. Glass block was used in the shed dormer on the front elevation.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 721 South 5th Street

ROLL-IMAGE # 70552 - 22

CD-IMAGE # 0602 - 22



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☐ Good
- ☒ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Craftsman bungalow

Exterior Walls (Current): Clapboard

Architectural Features: _____

Exterior Walls (Original): Clapboard

Date of Construction: 1926

Foundation: Textured CMU

Source: Township Assessor's Office

Roof Type/Material: Side gable/Asphalt shingle

Overall Plan Configuration: Simple rectangle

Window Material/Type: Wd trim/alum/DbI Hung

ARCHITECTURAL FEATURES: Wide eaves, exposed rafter tails, and wooden brackets typify the Craftsman style. The roof-line breaks at the front porch and continues at a shallower slope. A single gabled roof dormer is centered on the front elevation. The entrance is placed off to the south side of the house and is sheltered with a hipped roof supported by large wooden brackets. Most of the windows are grouped together around the house. There are no corner boards used to trim the siding.

ALTERATIONS: The front porch has been closed in and a group of seven windows have been inserted in the opening. Shutters have been added. These do not belong to the design vocabulary of this style.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 724 South 5th Street

ROLL-IMAGE # 70551 - 8

CD-IMAGE # 0601 - 80



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Craftsman Bungalow

Exterior Walls (Current): Composite patterned shingle

Architectural Features: _____

Exterior Walls (Original): Clapboard

Date of Construction: 1926

Foundation: Textured CMU

Source: Township Assessor's Office

Roof Type/Material: Side gable/Asphalt shingle

Overall Plan Configuration: Simple rectangle

Window Material/Type: Wd/DbI Hung

ARCHITECTURAL FEATURES: The eaves are relatively narrow for the style. There are no wooden brackets but there are exposed rafter tails at the main eaves. The roof slope breaks at the front porch and the roof supports are not clearly expressed. A single gabled roof dormer is centered on the front elevation. The front door to the porch is not centered and there is little decorative detailing in the trim surrounding it.

ALTERATIONS:



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 725 South 5th Street

ROLL-IMAGE # 70552 - 21

CD-IMAGE # 0602 - 21



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Eclectic - Tudor</u>	Exterior Walls (Current):	<u>Aluminum</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard</u>
Date of Construction:	<u>1928</u>	Foundation:	<u>Concrete/Brick</u>
Source:	<u>Township Assessor's Office</u>	Roof Type/Material:	<u>Cross gable/Asphalt shingle</u>
Overall Plan Configuration:	<u>Simple rectangle</u>	Window Material/Type:	<u>Aluminum/Dbl Hung</u>

ARCHITECTURAL FEATURES: The roof is steeply sloped (16:12 est.) and the eaves are narrow. The front door is not centered but is emphasized by its own gabled roof. Four windows are ganged together on the front elevation. Most of the rest of the windows around the house are paired.

ALTERATIONS: Most, if not all, of the original details were concealed or removed when the house was aluminized. Aluminum railings were added to the front steps in a recent remodeling.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 732 South 5th Street

ROLL-IMAGE # 70551 - 9

CD-IMAGE # 0601 - 81



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Craftsman Bungalow – orig.

Architectural Features: _____

Date of Construction: 1929

Source: Township Assessor's Office

Overall Plan Configuration: Simple rectangle

Exterior Walls (Current): Aluminum

Exterior Walls (Original): Clapboard

Foundation: Wire cut CMU

Roof Type/Material: Front gable/ Asphalt shingle

Window Material/Type: Alum/Dbf Hung

ARCHITECTURAL FEATURES: The original design featured a continuous eave that encircled the entire house. The original eaves featured wooden brackets and exposed rafter tails. The eaves are still open but are covered with aluminum. Most of the windows around the house are paired with the exception of the closed in front porch.

ALTERATIONS: All of the exposed rafter tails were concealed when the house was re-sided in aluminum. Only two of the brackets that supported the roof remain but are partially concealed with aluminum cladding. A large shed dormer has been added to the north and south elevations neither are appropriately scaled nor detailed for the original style.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 733 South 5th Street

ROLL-IMAGE # 70552 - 20

CD-IMAGE # 0602 - 20



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Eclectic - 4 square orig.

Exterior Walls (Current): Brick/Stucco

Architectural Features: _____

Exterior Walls (Original): Brick

Date of Construction: 1923

Foundation: Concrete

Source: Township Assessor's Office

Roof Type/Material: Hipped/Asphalt shingle

Overall Plan Configuration: 4 square w/ additions

Window Material/Type: Wd trim/Alum/Dbf Hung

ARCHITECTURAL FEATURES: The front door is off centered and is placed in its own gabled entry vestibule. A stucco/half timber gable form is a prominent feature of the street elevation. It was added at the time of a substantial remodeling of the house that included the entry vestibule and the rear addition.

ALTERATIONS: A large one-story addition was made to the rear of the house. It features a hipped roof and stucco/half timber wall finishes. The addition has no relationship with the original style.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL: