



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 500 Cedar Street

ROLL-IMAGE # 3432 - 29

CD-IMAGE # 4367 - 29



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☒ Excellent
- ☐ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Craftsman Bungalow

Exterior Walls (Current): Brick

Architectural Features:

Exterior Walls (Original): Brick

Date of Construction: 1911

Foundation: Concrete

Source: Township Assessors Office

Roof Type/Material: Side gable/Asphalt

Overall Plan Configuration: Simple - massed

Window Material/Type: Alum/Wd/Double hung

ARCHITECTURAL FEATURES: The large centered roof dormer and the closed in front porch are prominent features of the front elevation. The windows on the dormer feature a 3:1 pattern and an arched head. Stepped wooden brackets support the wide eaves on the side elevations as well as the dormer. Square brick columns support the roof of the all season porch. As this house is sited on a corner, the entrance is on the protected side (west) of the house.

ALTERATIONS:



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT: _____

Source _____

BUILDER: _____

Source _____

ASSOCIATED EVENTS, PEOPLE & DATES: _____

Source _____

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL: _____

STATE: _____

COUNTY: _____

LOCAL: _____



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 508 Cedar Street

ROLL-IMAGE # 3432 - 28

CD-IMAGE # 4367 - 28



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☒ Excellent
- ☐ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Victorian/Queen Anne</u>	Exterior Walls (Current):	<u>Aluminum on wood frame</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard on wood frame</u>
Date of Construction:	<u>1910</u>	Foundation:	<u>Concrete</u>
Source:	<u>Township Assessors Office</u>	Roof Type/Material:	<u>Hipped w/lower cross gables</u>
Overall Plan Configuration:	<u>Simple - massed</u>	Window Material/Type:	<u>Alum/Double hung</u>

ARCHITECTURAL FEATURES: The roofs are steep and the house has typical massing for this style. The full width front porch is the prominent architectural feature of the front elevation. The paired double hung windows located on the 2F of the front gable are narrow and have no muntins.

ALTERATIONS: There is an addition to the rear of the house that has a shallow pitched roof and an elevated wooden deck. These additions are non-sympathetic to the original house. The front porch has been filled in and is sheathed in vertical aluminum siding. The windows feature a 3:1 muntin pattern. All of the aluminum trim, windows, and siding are new.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT: _____

Source _____

BUILDER: _____

Source _____

ASSOCIATED EVENTS, PEOPLE & DATES: _____

Source _____

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL: _____

STATE: _____

COUNTY: _____

LOCAL: _____



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 514 Cedar Street

ROLL-IMAGE # 3432 - 27

CD-IMAGE # 4367 - 27



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	National	Exterior Walls (Current):	Clapboard
Architectural Features:		Exterior Walls (Original):	Clapboard
Date of Construction:	1910	Foundation:	Parged masonry
Source:	Township Assessors Office	Roof Type/Material:	Front gable/Asphalt
Overall Plan Configuration:	Simple - rectangle	Window Material/Type:	Alum/Double hung

ARCHITECTURAL FEATURES: A moderate roof slope and heavy frieze suggest some relation to the Greek revival style. There is also a simple classic wood molding profile at the head of the windows. The full width front porch is closed in for four season use.

ALTERATIONS: An addition to the rear of the house is sympathetic to the original featuring the same siding and a gable roof.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 517 Cedar Street

ROLL-IMAGE # 101 - 14

CD-IMAGE # 4405 - 14



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☐ Good
- ☒ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Victorian/Queen Anne</u>	Exterior Walls (Current):	<u>Aluminum/Wd Shingles</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard/Wd Shingles</u>
Date of Construction:	<u>1915</u>	Foundation:	<u>Textured CMU</u>
Source:	<u>Township Assessors Office</u>	Roof Type/Material:	<u>Hipped w/ lower cross gables/ Asphalt Shingles</u>
Overall Plan Configuration:	<u>Simple w/Irregularities</u>	Window Material/Type:	<u>Alum/Dbl Hung</u>

ARCHITECTURAL FEATURES: Elements of the original house that remain visible, aside from the overall massing, are the wood shingles in the gable ends and the entry porch. The house is somewhat unusual in that its side is oriented to the street with the entry & porch facing the side yard. Smooth Doric columns support the shed styled roof with a small gable form placed over the entry. The two-story bay element on the north elevation is the most important visual element of the street façade.

ALTERATIONS: The siding and windows have been replaced with aluminum. There is a small sun-porch located on the street elevation that is ironic in that it is the northeast corner of the house.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 521 Cedar Street

ROLL-IMAGE # 101 - 15

CD-IMAGE # 4405 - 15



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Prairie Four square</u>	Exterior Walls (Current):	<u>Brick</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Brick</u>
Date of Construction:	<u>1925</u>	Foundation:	<u>Concrete</u>
Source:	<u>Township Assessors Office</u>	Roof Type/Material:	<u>Hipped/Asphalt shingle</u>
Overall Plan Configuration:	<u>Simple square</u>	Window Material/Type:	<u>Alum/Wd/Dbl Hung</u>

ARCHITECTURAL FEATURES: There is a single hipped dormer located on the front side of the house roof. The full width front porch is the dominant architectural feature. Simple square brick columns support the roof of the porch. The double hung windows feature a 4:1 muntin pattern. All of the windows are used in pairs or groups of three.

ALTERATIONS: The soffits are boxed in aluminum. There is a small mudroom vestibule added to the rear of the house that is sheathed with dryvit and has a prefab greenhouse window unit. The porch appears to have been closed in subsequent to the initial construction and the entrance moved to the outer wall. Low brick side-walls were recently added at the front stairs.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT

ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 522 Cedar Street

ROLL-IMAGE # 3432 - 26

CD-IMAGE # 4367 - 26



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Prairie Foursquare</u>	Exterior Walls (Current):	<u>Brick</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Brick</u>
Date of Construction:	<u>1890</u>	Foundation:	<u>Brick/Concrete</u>
Source:	<u>Township Assessors Office</u>	Roof Type/Material:	<u>Hipped/Asphalt shingle</u>
Overall Plan Configuration:	<u>Simple square</u>	Window Material/Type:	<u>Wd Trim/Alum/Dbt Hung</u>

ARCHITECTURAL FEATURES: Hipped dormers are placed on the front and side elevations of the roof. The hipped roof flares at the eaves. Wooden Doric columns, with bases on the porch deck, support the roof of the porch. The columns are more of a Colonial Revival reference than a Prairie style detail. A plain wooden railing with square balusters encircles the porch. The stone belt course that marks the first floor line also separates two brick colors emphasizing the horizontal line of the house. These features, along with the wide roof overhangs, are commonly used design elements of the style. The single story bay window on the west side features open brick corners. Most of the windows have stone lintels and sills.



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

522 Cedar Street - Continuation Sheet

ALTERATIONS: A wooden two-story porch with a shed roof was added to the rear of the house. Its design and detailing are inconsistent with the original design.

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 606 Cedar Street

ROLL-IMAGE # 3432 - 25

CD-IMAGE # 4367 - 25



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	National	Exterior Walls (Current):	Aluminum
Architectural Features:		Exterior Walls (Original):	Clapboard
Date of Construction:	1870 Orig.	Foundation:	Stone / Orig., Conc. / Adds
Source:	Township Assessors Office	Roof Type/Material:	Side gable/Asphalt Shingle
Overall Plan Configuration:	Simple rectangle – Orig.	Window Material/Type:	Alum/DbI Hung

ARCHITECTURAL FEATURES: This house has narrow eaves and shallow roof slope. The lack of windows on the second floor of the front elevation is odd as is the window arrangement on the side elevation. Two square columns support a small gable roofed porch that protects the front door.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

606 Cedar Street - Continuation Sheet

ALTERATIONS: Little of the original house is revealed in its current condition. It appears that the aluminum siding and ill-conceived additions have concealed much. The two-story addition to the rear does not relate to the original architecture in any way. A two-story wooden deck that was added to the north of this addition does not relate to the addition or the original house. A small one-story addition featuring an octagonal window was made to the west side of the house.

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 610 Cedar Street

ROLL-IMAGE # 3432 - 24

CD-IMAGE # 4367 - 24



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: Modern/Colonial Revival

Exterior Walls (Current): Aluminum

Architectural Features: _____

Exterior Walls (Original): Aluminum

Date of Construction: 1978

Foundation: Concrete

Source: Township Assessors Office

Roof Type/Material: Side Gable/Asphalt Shingle

Overall Plan Configuration: Compound - L

Window Material/Type: Aluminum/Asphalt Shingle

ARCHITECTURAL FEATURES: The two-car garage dominates the street elevation. It does not relate to the main part of the house. The roof slope is shallow and the overhangs are narrow. A large three-part picture window is an important element of the front façade.

ALTERATIONS:



ARCHITECTURAL SURVEY
NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

**REPRESENTATION IN EXISTING
SURVEYS:**

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 612 Cedar Street

ROLL-IMAGE # 3432 - 23

CD-IMAGE # 4367 - 23



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☐ Good
- ☒ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: National

Architectural Features: _____

Date of Construction: 1860

Source: Township Assessors Office

Overall Plan Configuration: Simple – Rectangle (orig)

Exterior Walls (Current): Stucco on masonry

Exterior Walls (Original): Masonry

Foundation: _____

Roof Type/Material: Side gable/Asphalt shingle

Window Material/Type: Alum/Dbf Hung

ARCHITECTURAL FEATURES: This house appears to be related stylistically to the house located up the street at 606 Cedar. The first floor of this house is raised off grade and consequently has steps and a small raised porch at the front door. The roof pitch is shallow and the eaves are narrow. There are exposed rafter tails at the eaves. Two small windows with short head heights are placed on the front elevation at the eave. The windows sills of the original house are articulated. Two square columns support a small gable roofed front porch.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

612 Cedar Street - Continuation Sheet

ALTERATIONS: Two additions to the north side of the house have been made. The first is two-stories with a broad gabled roof and is sheathed in a wavy-patterned Masonite siding. The second is a single –story with a shed roof and is also sided with the wavy Masonite. Neither addition relates to the original design.

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 615 Cedar Street

ROLL-IMAGE # 3432 - 21

CD-IMAGE # 4367 - 21



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type: <u>Colonial Revival/Cape Cod</u>	Exterior Walls (Current): <u>Clapboard</u>
Architectural Features: _____	Exterior Walls (Original): <u>Clapboard</u>
Date of Construction: <u>1925</u>	Foundation: <u>Concrete</u>
Source: <u>Township Assessors Office</u>	Roof Type/Material: <u>Side Gable/Asphalt shingle</u>
Overall Plan Configuration: <u>Simple Rectangle</u>	Window Material/Type: <u>Wd Trim/Alum/Dbf Hung</u>

ARCHITECTURAL FEATURES: The broad front roof plane flares to cover the porch. 4 square wooden columns originally supported the porch roof. A large shed roofed dormer is placed symmetrically on the front roof. The front door is centered on the front elevation too.

ALTERATIONS: The front porch has been screened in and low clapboard sided walls have been added.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL:

STATE:

COUNTY:

LOCAL:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 621 Cedar Street

ROLL-IMAGE # 3432 - 20

CD-IMAGE # 4367 - 20



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	<u>Victorian/Shingle Style</u>	Exterior Walls (Current):	<u>Clapboard/Wood shingles</u>
Architectural Features:	<u></u>	Exterior Walls (Original):	<u>Clapboard</u>
Date of Construction:	<u>1925</u>	Foundation:	<u>Concrete</u>
Source:	<u>Township Assessors Office</u>	Roof Type/Material:	<u>Hipped Side Gable / Asphalt shingle</u>
Overall Plan Configuration:	<u>Simple Square</u>	Window Material/Type:	<u>Wd trim/Alum/ Dbl Hung</u>

ARCHITECTURAL FEATURES: This house possesses a charming street scale. The placement of the ½ tower on the corner relates well to the corner lot. The hip on gable roof gently flares over the porch. Square columns support the porch roof. A shed-roofed dormer is placed over the porch. The floor lines are clearly defined with wood trim. The upper story is covered with wood fish-scale shingles. The scale of this small house is manipulated by being located on an elevated lot with a raised first floor.

ALTERATIONS:



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT: _____

Source _____

BUILDER: _____

Source _____

ASSOCIATED EVENTS, PEOPLE & DATES: _____

Source _____

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL: _____

STATE: _____

COUNTY: _____

LOCAL: _____



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 622 Cedar Street

ROLL-IMAGE # 3432 - 19

CD-IMAGE # 4367 - 19



ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☒ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- ☐ Excellent
- ☒ Good
- ☐ Fair
- ☐ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	Craftsman Bungalow	Exterior Walls (Current):	Clapboard w/brick front porch
Architectural Features:		Exterior Walls (Original):	Clapboard
Date of Construction:	1925	Foundation:	Parged masonry – Orig.
Source:	Township Assessors Office	Roof Type/Material:	Hipped Side gable/ Asphalt Shingle
Overall Plan Configuration:	Simple rectangle	Window Material/Type:	Alum/Dbf Hung

ARCHITECTURAL FEATURES: The overall character of the house is Craftsman even though there are few details to further support the style. There is an absence of wood details at the open eaves.....no exposed rafter tails or brackets.

ALTERATIONS: The brick appears to have been added when the front porch was closed in. There is a large 2-story addition to the rear that has a gable roof and detailing similar to the original house. The addition has a concrete foundation.



ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

Secondary Structure

ADDRESS

ROLL-IMAGE # _____

CD-IMAGE # _____

HISTORIC INFORMATION:

ARCHITECT:

Source

BUILDER:

Source

ASSOCIATED EVENTS, PEOPLE & DATES:

Source

REPRESENTATION IN EXISTING SURVEYS:

FEDERAL:

STATE:

COUNTY:

LOCAL: