



# ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT  
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

## Primary Structure

ADDRESS 513 Illinois Street

ROLL-IMAGE # 3178 - 3

CD-IMAGE # 032D - 3



## ARCHITECTURAL SIGNIFICANCE

- Significant
- Contributing
- Non-Contributing
- Potential for Individual National Register Designation

## BUILDING CONDITION

- Excellent
- Good
- Fair
- Poor

## ARCHITECTURAL INFORMATION

Architectural Style/Type: Craftsman/ 4 square

Exterior Walls (Current): Clapboard

Architectural Features: \_\_\_\_\_

Exterior Walls (Original): Clapboard

Date of Construction: 1920

Foundation: Rock faced Concrete block

Source: Township Assessor's Office

Roof Type/Material: Hipped/Asphalt

Overall Plan Configuration: Simple/4 square

Window Material/Type: Alum/Wood/Double Hung

**ARCHITECTURAL FEATURES:** The roof has open eaves with exposed rafter tails. A large roof dormer that has a hipped roof is centered on the front entrance. There is some nice simple detailing around the porch and the window openings. Simply detailed round wood columns bearing on a handrail height wall that encircles the porch support the roof of the full width front porch.

**ALTERATIONS:**



ST. CHARLES  
SINCE 1834

ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
NEAR WEST HISTORIC DISTRICT  
ST. CHARLES, ILLINOIS

513 Illinois Street - Continuation Sheet

**HISTORIC INFORMATION:**

---

**ARCHITECT:**

Source

**BUILDER:**

Source

**ASSOCIATED EVENTS, PEOPLE & DATES:**

Source

**REPRESENTATION IN EXISTING  
SURVEYS:**

---

**FEDERAL:**

**STATE:**

**COUNTY:**

**LOCAL:**



# ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT  
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

## Primary Structure

ADDRESS 515 Illinois Street

ROLL-IMAGE # 3299 - 7

CD-IMAGE # 3739 - 7



## ARCHITECTURAL SIGNIFICANCE

- Significant
- Contributing
- Non-Contributing
- Potential for Individual National Register Designation

## BUILDING CONDITION

- Excellent
- Good
- Fair
- Poor

## ARCHITECTURAL INFORMATION

Architectural Style/Type: National/Cottage

Exterior Walls (Current): Clapboard

Architectural Features: \_\_\_\_\_

Exterior Walls (Original): Clapboard

Date of Construction: 1895

Foundation: Parged masonry

Source: Township Assessor's Office

Roof Type/Material: Cross gable/Asphalt shingle

Overall Plan Configuration: Simple rectangle

Window Material/Type: Wd/Alum/Dbl hung

**ARCHITECTURAL FEATURES:** The gable form dominates the façade of this small-scaled house. The entry is asymmetrically placed. A frieze board is used at the wall/roof juncture. Corner boards are used to trim the siding at the corners. A break in the roof plane occurs as the main roof approaches the front of the house.

**ALTERATIONS:** The front entry area was remodeled at some point. The windows sizes and configuration is atypical of the rest of the house. The foundation appears to be concrete. An addition appears to have been made to the rear of the house as a small shed roofed area can be seen from the street.



ST. CHARLES  
SINCE 1834

ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
NEAR WEST HISTORIC DISTRICT  
ST. CHARLES, ILLINOIS

Continuation Sheet

**HISTORIC INFORMATION:**

---

**ARCHITECT:** \_\_\_\_\_

Source \_\_\_\_\_

**BUILDER:** \_\_\_\_\_

Source \_\_\_\_\_

**ASSOCIATED EVENTS, PEOPLE & DATES:** \_\_\_\_\_

Source \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

**REPRESENTATION IN EXISTING  
SURVEYS:**

---

**FEDERAL:** \_\_\_\_\_

**STATE:** \_\_\_\_\_

**COUNTY:** \_\_\_\_\_

**LOCAL:** \_\_\_\_\_



# ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT  
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

## Primary Structure

ADDRESS 601 Illinois Street

ROLL-IMAGE # 70549 - 24

CD-IMAGE # 0601 - 24



## ARCHITECTURAL SIGNIFICANCE

- Significant
- Contributing
- Non-Contributing
- Potential for Individual National Register Designation

## BUILDING CONDITION

- Excellent
- Good
- Fair
- Poor

## ARCHITECTURAL INFORMATION

Architectural Style/Type: <u>National/Front gable</u>	Exterior Walls (Current): <u>Aluminum</u>
Architectural Features: _____	Exterior Walls (Original): <u>Clapboard</u>
Date of Construction: <u>1910</u>	Foundation: <u>Textured Concrete Block</u>
Source: <u>Township Assessor's Office</u>	Roof Type/Material: <u>Front gable/Asphalt</u>
Overall Plan Configuration: <u>Compound L w/ additions</u>	Window Material/Type: <u>Aluminum/Double hung</u>

**ARCHITECTURAL FEATURES:** 1 ½ story with roof dormers on the east and west elevations. This house has a three season front porch and associated front steps that were probably later additions.

**ALTERATIONS:** 1 story additions to the west and south sides have a gabled and flat roof areas. These additions do not relate well to the scale of the original house. The foundation skirt of the front porch has vertical aluminum siding which is not typical of the rest of the house.



ST. CHARLES  
SINCE 1834

ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
NEAR WEST HISTORIC DISTRICT  
ST. CHARLES, ILLINOIS

601 Illinois Street - Continuation Sheet

**HISTORIC INFORMATION:**

---

**ARCHITECT:** \_\_\_\_\_

Source \_\_\_\_\_

**BUILDER:** \_\_\_\_\_

Source \_\_\_\_\_

**ASSOCIATED EVENTS, PEOPLE & DATES:** \_\_\_\_\_

Source \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**REPRESENTATION IN EXISTING  
SURVEYS:**

---

**FEDERAL:** \_\_\_\_\_

**STATE:** \_\_\_\_\_

**COUNTY:** \_\_\_\_\_

**LOCAL:** \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



# ARCHITECTURAL SURVEY

NEAR WEST HISTORIC DISTRICT  
ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

## Primary Structure

ADDRESS 610 Illinois Street

ROLL-IMAGE # 3435 - 13

CD-IMAGE # 4369 - 13



## ARCHITECTURAL SIGNIFICANCE

- Significant
- Contributing
- Non-Contributing
- Potential for Individual National Register Designation

## BUILDING CONDITION

- Excellent
- Good
- Fair
- Poor

## ARCHITECTURAL INFORMATION

Architectural Style/Type: Colonial revival/Cape Cod

Exterior Walls (Current): Vinyl on wood frame

Architectural Features: \_\_\_\_\_

Exterior Walls (Original): Vinyl on wood frame

Date of Construction: 1988

Foundation: Concrete

Source: Township Assessor's Office

Roof Type/Material: Side gable/Asphalt

Overall Plan Configuration: Simple rectangle

Window Material/Type: Aluminum/double hung

**ARCHITECTURAL FEATURES:** This is new construction. It is a simply detailed interpretation of the original Colonial style. The proportion of the roof to the main body of the house is incorrect, as the slope is not steep enough. The roof dormers are oversized and are out of proportion. This Cape Cod is oversimplified and lacks any of the classic detailing that is commonly part of this style.



ST. CHARLES  
SINCE 1834

ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
NEAR WEST HISTORIC DISTRICT  
ST. CHARLES, ILLINOIS

Continuation Sheet

**Secondary Structure**

ADDRESS

ROLL-IMAGE # \_\_\_\_\_

CD-IMAGE # \_\_\_\_\_

**HISTORIC INFORMATION:**

**ARCHITECT:** \_\_\_\_\_

Source \_\_\_\_\_

**BUILDER:** \_\_\_\_\_

Source \_\_\_\_\_

**ASSOCIATED EVENTS, PEOPLE & DATES:** \_\_\_\_\_

Source \_\_\_\_\_

**REPRESENTATION IN EXISTING  
SURVEYS:**

**FEDERAL:** \_\_\_\_\_

**STATE:** \_\_\_\_\_

**COUNTY:** \_\_\_\_\_

**LOCAL:** \_\_\_\_\_