

NEAR WEST HISTORIC DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SIGNIFICANCE

- □ Significant
- □ Contributing
- ► Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- Excellent
- ► Good
- Fair
- □ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	Folk eclectic	Exterior Walls (Current):	The garage is alum/brick and the house is clapboard/brick.
Architectural Features:		Exterior Walls (Original):	Clapboard/brick.
Date of Construction: Source:	1940 Township Assessor's Office	Foundation: Roof Type/Material:	Concrete Hipped with a lower side gable/asphalt shingle/flat with built –up roofing
Overall Plan Configuration:	Compound	Window Material/Type:	Alum/dbl. hung

ARCHITECTURAL FEATURES:

The main body of the house features a porch that wraps around the north and east sides. 4x4 posts with no special details support it. The front of the house features a small round window centered over the front door (east elevation).



NEAR WEST HISTORIC DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Continuation Sheet

ALTERATIONS: The garage addition on the west side of the house has a flat roof and is poorly proportioned to the rest of the house. A small addition to the south side has a hipped roof. The link between the garage and the main body of the house has a lower gabled roof. All of the siding, colors, and detailing appear to be compatible...though the garage is sided in aluminum and the main house is sided in brick and clapboard.

HISTORIC INFORMATION:	
ARCHITECT:	
Source	
<u> </u>	
BUILDER: _	
Source _	
ASSOCIATED EVENTS, PEOPLE & DATES:	
Source _	
_	
-	
<u> </u>	
<u> </u>	
_	
_	
-	
REPRESENTATION IN EXISTING	
SURVEYS:	
FEDERAL: _	
STATE:	
COUNTY:	
LOCAL:	



NEAR WEST HISTORIC DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- Contributing
- □ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- Excellent
- ► Good
- □ Fair
- □ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	Eclectic – Simplified Tudor	Exterior Walls (Current):	Clapboard
Architectural Features:		Exterior Walls (Original):	Clapboard
Date of Construction: Source:	1932 Township Assessor's Office	Foundation: Roof Type/Material:	Concrete Cross-Gable/asphalt
Overall Plan Configuration:	Compound - L	Window Material/Type:	Aluminum/Double hung

ARCHITECTURAL FEATURES: Charming front entry porch that features an arched soffit supported by nicely detailed square columns. The railing is also nicely detailed. The steeply sloped roof adds to the character of this house – the slope exceeds 12:12. The main roof wraps around the sides and breaking down the scale of those facades and adding interest. Multiple front gables also add to the charm of the façade. The windows feature a 6:1 muntin pattern.



NEAR WEST HISTORIC DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

509 Walnut Street - Continuation Sheet

ALTERATIONS: It appears that the front porch was added at a later date.

HISTORIC INFORMATION:	
ARCHITECT:	
Source	
_	
BUILDER:	
Source	
_	
ASSOCIATED EVENTS, PEOPLE & DATES:	
Source	
<u>-</u>	
<u>-</u>	
<u>-</u>	
-	
-	
-	
-	
REPRESENTATION IN EXISTING	
SURVEYS:	
_	
FEDERAL:	
STATE:	
COUNTY:	
LOCAL:	



NEAR WEST HISTORIC DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 511 Walnut Street

ROLL-IMAGE # <u>3435 - 8</u>

CD-IMAGE # 4369 - 8



ARCHITECTURAL SIGNIFICANCE

- Significant
- □ Contributing
- ☐ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- Excellent
- ► Good
- Fair
- □ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	Greek Revival	Exterior Walls (Current):	Brick
Architectural Features:		Exterior Walls (Original):	Brick
Date of Construction: Source:	1875 Township Assessor's Office	Foundation: Roof Type/Material:	Stone Cross gable/Asphalt
Overall Plan Configuration:	1	Window Material/Type:	

ARCHITECTURAL FEATURES: A large front gable dominates the front of the house. A heavy frieze band located at the roof line is broken at the front elevation. There is a prominent entrance detailed in the classical tradition in wood. Stone lintels and sills are typical around the house. The window pattern is 6:6.



NEAR WEST HISTORIC DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

511 Walnut St. - Continuation Sheet

ALTERATIONS: The original roof was undoubtedly wood shakes or shingles. There have been several additions constructed with both brick and clapboard exteriors. Some of the additions are 1 story adding to the rambling character of the house. Some of the 1 story elements have flat roofs.

HISTORIC INFORMATION:	
ARCHITECT:	
Source	
BUILDER:	
Source	
ASSOCIATED EVENTS, PEOPLE & DATES:	
Source	
REPRESENTATION IN EXISTING	
SURVEYS:	
FEDERAL:	
STATE:	YES
COUNTY:	
LOCAL:	There is a local landmark plaque located at the front door, however, there is no documentation to that effect. The plaque that this is known as the Elisha Freeman house.



NEAR WEST HISTORIC DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 622 Walnut Street

ROLL-IMAGE # <u>3435 - 2</u>

CD-IMAGE # <u>4369 - 2</u>



ARCHITECTURAL SIGNIFICANCE

- Significant
- ► Contributing
- □ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- Excellent
- Good
- ▶ Fair
- □ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	Gothic revival/Gable front &	Exterior Walls (Current):	Clapboard
Architectural Features:	wing	Exterior Walls (Original):	Clapboard
	1000	,	•
Date of Construction:			Parged Masonry
Source:	Township Assessor's Office	Roof Type/Material:	Cross gable/Asphalt
Overall Plan Configuration:	Compound L	Window Material/Type:	Aluminum/Double hung

ARCHITECTURAL FEATURES: The front gable has distinct vertical proportions & steep roof slope. There is a partial width front porch that has a shed type roof that is supported by turned columns. All of the windows have simple wood trim. The siding has relatively wide trim @ the eaves and corners. There is a small rear entry that retains the detail character of the front porch. The eaves are open by are soffited in line w/ the roof slope.

ALTERATIONS: This roof probably had wood shakes or shingles originally.



NEAR WEST HISTORIC DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

622 Walnut Street - Continuation Sheet

HISTORIC INFORMATION:	
ARCHITECT:	
Source	
BUILDER:	
Source	
ASSOCIATED EVENTS, PEOPLE & DATES:	
Source	
REPRESENTATION IN EXISTING	
SURVEYS:	
FEDERAL:	
STATE:	
COUNTY:	
LOCAL:	



NEAR WEST HISTORIC DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure	
ADDRESS 623 Walnut Street ROLL-IMAGE # _3435 - 16	
CD-IMAGE # 4369 - 16	

ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ► Contributing
- □ Non-Contributing
- ☐ Potential for Individual National Register Designation

BUILDING CONDITION

- Excellent
- Good
- ► Fair
- Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	National/Front Gable	Exterior Walls (Current):	Masonite
Architectural Features:		Exterior Walls (Original):	Unknown
	1910 Township Assessor's Office		Concrete Front Gable/Asphalt
Overall Plan Configuration:	Simple	Window Material/Type:	Wood & Alum./Dbl. Hung

ARCHITECTURAL FEATURES: Simple house with plain wood detailing around all of the openings. There are shed roof dormers on both the east and west sides. The windows have a 6:6 muntin pattern. This house is consistent in scale and architectural character with the majority of the other houses in this neighborhood. It is one of the older houses in the neighborhood.

ALTERATIONS: The front porch, constructed with wolmanized lumber, is not compatible with the original house. There is a 2F entrance on the east elevation that is constructed over a side entrance that is also not compatible.



NEAR WEST HISTORIC DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

623 Walnut Street - Continuation Sheet

HISTORIC INFORMATION:	
ARCHITECT:	
Source	
BUILDER:	
Source	
ASSOCIATED EVENTS, PEOPLE & DATES:	
Source	
REPRESENTATION IN EXISTING	
SURVEYS:	
FEDERAL:	
STATE:	
COUNTY:	
LOCAL:	