



ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
**ST. CHARLES CENTRAL DISTRICT**  
**ST. CHARLES, ILLINOIS**

DIXON ASSOCIATES / ARCHITECTS

**ARCHITECTURAL INTEGRITY**

	1	2	3
<input type="checkbox"/> Unaltered	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Minor Alteration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Major Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Additions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sensitive to original	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1: first floor; 2: upper floors; 3: roof/cornice

**BUILDING CONDITION**

- Excellent: Well-maintained**
- Good: Minor maintenance needed**
- Fair: Major repairs needed**
- Poor: Deteriorated**

**ARCHITECTURAL DESCRIPTION**

**Style:** Greek Revival

**Date of Construction:** ca. 1840's

**Source:** A Field Guide to American Houses

**Features:**

Rough limestone exterior with cut limestone window beads and sills. East porch and north section added. Board and batten sided garage added.

**ARCHITECTURAL SIGNIFICANCE**

- Significant**
- Contributing**
- Non-Contributing**



**Address:**

316 West Cedar Street

**Representation in Existing Surveys:**

- Federal**
- State**
- County**
- Local**

**Block No. 2**

**Building No. 2**

**SURVEY DATE:**

**MAY 1994**

**ROLL NO. 1**

**NEGATIVE NO. 28**



ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
ST. CHARLES CENTRAL DISTRICT  
ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

CONTINUATION SHEET NO: 1



ROLL NO. 1

NEGATIVE NO. 29

**Address:**

316 West Cedar Street

**Remarks:**

Garage

Block No. 2

Building No. 2

**Address:**

**Remarks:**

Block No.

Building No.

ROLL NO.

NEGATIVE NO.



ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
**ST. CHARLES CENTRAL DISTRICT**  
**ST. CHARLES, ILLINOIS**

DIXON ASSOCIATES / ARCHITECTS

**ARCHITECTURAL INTEGRITY**

	1	2	3
<input type="checkbox"/> Unaltered	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Minor Alteration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Major Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Additions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1: first floor; 2: upper floors; 3: roof/cornice

**ARCHITECTURAL SIGNIFICANCE**

- Significant
- Contributing
- Non-Contributing

**BUILDING CONDITION**

- Excellent: Well-maintained
- Good: Minor maintenance needed
- Fair: Major repairs needed
- Poor: Deteriorated

**ARCHITECTURAL DESCRIPTION**

**Style:** Greek Revival

**Date of Construction:** ca. 1840's

**Source:** A Field Guide to American Houses

**Features:**

Rough limestone exterior with cut limestone window heads and sills at first floor, brick window heads at south elevation, second floor. Porch and perimeter low stone wall added in 1990's. Fan lite at south gable end filled with stone.



**Address:**

322 West Cedar Street

**Representation in Existing Surveys:**

- Federal
- State
- County
- Local

**Block No. 2**

**Building No. 1**

**SURVEY DATE:**

MAY 1994

**ROLL NO. 1**

**NEGATIVE NO. 27**



ST. CHARLES HISTORIC PRESERVATION COMMISSION

# ARCHITECTURAL SURVEY ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

CONTINUATION SHEET NO: 1



**Address:**

322 West Cedar Street

**Remarks:**

West side, wrap around porch added in 1990's.

**Block No. 2**

**Building No. 1**

**ROLL NO. 12**

**NEGATIVE NO. 27**

**Address:**

322 West Cedar Street

**Remarks:**

**Block No. 2**

**Building No. 1**

**ROLL NO.**

**NEGATIVE NO.**



ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
**ST. CHARLES CENTRAL DISTRICT**  
**ST. CHARLES, ILLINOIS**

DIXON ASSOCIATES / ARCHITECTS

**ARCHITECTURAL INTEGRITY**

	1	2	3
<input checked="" type="checkbox"/> Unaltered	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/> Minor Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Major Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Additions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1: first floor; 2: upper floors; 3: roof/cornice

**ARCHITECTURAL SIGNIFICANCE**

- Significant
- Contributing
- Non-Contributing

**BUILDING CONDITION**

- Excellent: Well-maintained
- Good: Minor maintenance needed
- Fair: Major repairs needed
- Poor: Deteriorated

**ARCHITECTURAL DESCRIPTION**

**Style:** Eclectic/Italian Renaissance

**Date of Construction:** 1912

**Source:** A Field Guide to American Houses

**Features:** St. Patrick Rectory

Brick structure with significant stone accents. Elaborate stone caps to masonry pilasters on south facade. Stone at upper facade matches church to east.



**Address:**

408 West Cedar Street

**Representation in Existing Surveys:**

- Federal
- State
- County
- Local

**Block No. 1**

**Building No. 4**

**SURVEY DATE:**

**MAY 1994**

**ROLL NO. 1**

**NEGATIVE NO. 24**



ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
**ST. CHARLES CENTRAL DISTRICT**  
**ST. CHARLES, ILLINOIS**

DIXON ASSOCIATES / ARCHITECTS

**ARCHITECTURAL INTEGRITY**

	1	2	3
<input checked="" type="checkbox"/> Unaltered	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/> Minor Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Major Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Additions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1: first floor; 2: upper floors; 3: roof/cornice

**ARCHITECTURAL SIGNIFICANCE**

- Significant
- Contributing
- Non-Contributing

**BUILDING CONDITION**

- Excellent: Well-maintained
- Good: Minor maintenance needed
- Fair: Major repairs needed
- Poor: Deteriorated

**ARCHITECTURAL DESCRIPTION**

**Style:** Eclectic/Italian Renaissance

**Date of Construction:** 1912

**Source:** A Field Guide to American Houses

**Features:** St. Patrick Church

Triple arch entry doors divided by masonry pilasters. Stone accents trim parapet and over central entry door at south. Similar stone detail at east elevation.



**Address:**

408 West Cedar Street

**Representation in Existing Surveys:**

- Federal
- State
- County
- Local

**Block No. 1**

**Building No. 3**

**SURVEY DATE:**

**MAY 1994**

**ROLL NO. 1**

**NEGATIVE NO. 25**



ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
ST. CHARLES CENTRAL DISTRICT  
ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

CONTINUATION SHEET NO: 1



**Address:**

408 West Cedar Street

**Remarks:**

East side

**Block No. 1**

**Building No.3**

**ROLL NO. 1**

**NEGATIVE NO. 26**

**Address:**

408 West Cedar Street

**Remarks:**

**Block No. 1**

**Building No.3**

**ROLL NO.**

**NEGATIVE NO.**