


ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY				BUILDING CONDITION
	1	2	3	☐ Excellent: Well-maintained
<b>□</b> Unaltered	$\boxtimes$	$\boxtimes$		☐ Good: Minor maintenance needed
☐ Minor Alteration				☐ Fair: Major repairs needed
☐ Major Alteration				☐ Poor: Deteriorated
☐ Additions  Sensitive to original  Insensitive to original  1: first floor; 2: upper floors;  ARCHITECTURAL SIGN  ☐ Significant	☐ 3: roo			ARCHITECTURAL DESCRIPTION  Style: Gothic Revival  Date of Construction: 1929-30  Source: Celebrating History  Features: St. Patrick School  Main facade at the south features stone trim in brick with Gothic arched windows. Arched entrance in stone projected out from face of building, capped with gable at parapet line. School building dedicated as George H.
☐ Contributing				Rempe Memorial.
☐ Non-Contributing				



ROLL NO. 1

**NEGATIVE NO. 23** 

#### Address:

120 North Fifth Street

# Representation in Existing Surveys:

- ☐ Federal
- ☐ State
- ☐ County
- ☐ Local

Block No. 1

**Building No. 5** 

**SURVEY DATE:** 

**MAY 1994** 




ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

### CONTINUATION SHEET NO: 1



Address:

120 North Fifth Street

Remarks:

West Elevation. Stone quoins on brick building. 2 1/2 stories plus decorative parapet with stone accents in brick.

**ROLL NO. 12** 

**NEGATIVE NO. 34** 

Block No. 1

Building No. 5

Address:

120 North Fifth Street

Remarks:

ROLL NO.

NEGATIVE NO.

Block No. 1

**Building No. 5** 



ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTE	GRI'	TY	BUILDING CONDITION
1	2	3	☐ Excellent: Well-maintained
☑ Unaltered ☑	$\boxtimes$	$\boxtimes$	☐ Good: Minor maintenance needed
☐ Minor Alteration ☐			☐ Fair: Major repairs needed
☐ Major Alteration ☐			☐ Poor: Deteriorated
☐ Additions ☐  Sensitive to original ☐  Insensitive to original ☐  1: first floor; 2: upper floors; 3: roo  ARCHITECTURAL SIGNIFIC			ARCHITECTURAL DESCRIPTION  Style: Modern  Date of Construction: 1958-59  Source: Field observation of date stone  Features: St. Patrick School  Simple bands of windows on each floor with cut stone frame. Flat roof and simple box forms contribute to
☐ Significant ☐ Contributing ☑ Non-Contributing			typical 1950's school building appearance.



**ROLL NO. 12** 

**NEGATIVE NO. 33** 

**SURVEY DATE:** 

**MAY 1994** 




ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

#### **CONTINUATION SHEET NO: 1**



Address:

120 North Fifth Street

Remarks:

North side facing State Street

**ROLL NO. 12** 

**NEGATIVE NO. 32** 

Block No. 1

**Building No. 1** 

Address:

120 North Fifth Street

Remarks:

ROLL NO.

**NEGATIVE NO.** 

Block No. 1

**Building No. 1**