



ST. CHARLES HISTORIC PRESERVATION COMMISSION

# ARCHITECTURAL SURVEY ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

## ARCHITECTURAL INTEGRITY

	1	2	3
<input type="checkbox"/> Unaltered	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Minor Alteration	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Major Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Additions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1: first floor; 2: upper floors; 3: roof/cornice

## BUILDING CONDITION

- Excellent: Well-maintained**
- Good: Minor maintenance needed**
- Fair: Major repairs needed**
- Poor: Deteriorated**

## ARCHITECTURAL DESCRIPTION

**Style:** Stick

**Date of Construction:** 1860-1890

**Source:** A Field Guide to American Houses

**Features:**

Cross gable roofs on two story structure with steeply sloping roofs and shingle texture in front facing gable ends. Mansard shingled hood over first floor window at front facade.

## ARCHITECTURAL SIGNIFICANCE

- Significant**
- Contributing**
- Non-Contributing**



**Address:**

15 North 6th Avenue

**Representation in Existing Surveys:**

- Federal**
- State**
- County**
- Local**

**Block No. 45**

**Building No. 3**

**SURVEY DATE:**

MAY 1994

ROLL NO. 15

NEGATIVE NO. 30



ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
ST. CHARLES CENTRAL DISTRICT  
ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

CONTINUATION SHEET NO: 1



**Address:**

15 North 6th Avenue

**Remarks:**

North Elevation.

**Block No. 45**

**Building No. 3**

**ROLL NO. 15**

**NEGATIVE NO. 29**

**Address:**

**Remarks:**

**Block No.**

**Building No.**

**ROLL NO.**

**NEGATIVE NO.**



ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
**ST. CHARLES CENTRAL DISTRICT**  
**ST. CHARLES, ILLINOIS**

DIXON ASSOCIATES / ARCHITECTS

**ARCHITECTURAL INTEGRITY**

	1	2	3
<input type="checkbox"/> Unaltered	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Minor Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Major Alteration	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input type="checkbox"/> Additions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1: first floor; 2: upper floors; 3: roof/cornice

**ARCHITECTURAL SIGNIFICANCE**

Significant

Contributing

Non-Contributing

**BUILDING CONDITION**

Excellent: Well-maintained

Good: Minor maintenance needed

Fair: Major repairs needed

Poor: Deteriorated

**ARCHITECTURAL DESCRIPTION**

**Style:** Greek Revival

**Date of Construction:** 1825-1860

**Source:** A Field Guide to American Houses

**Features:**

Front gabled broken pediment two story house. Synthetic siding. Full front porch.



**Address:**

117 North 6th Avenue

**Representation in Existing Surveys:**

Federal

State

County

Local

**Block No. 39**

**Building No. 2**

**SURVEY DATE:**

**MAY 1994**

**ROLL NO. 5**

**NEGATIVE NO. 20**



ST. CHARLES HISTORIC PRESERVATION COMMISSION

**ARCHITECTURAL SURVEY**  
**ST. CHARLES CENTRAL DISTRICT**  
**ST. CHARLES, ILLINOIS**

DIXON ASSOCIATES / ARCHITECTS

CONTINUATION SHEET NO: 1



**Address:**

117 North 6th Avenue

**Remarks:**

North Elevation.

**Block No. 39**

**Building No. 2**

**ROLL NO. 18**

**NEGATIVE NO. 17**



**Address:**

117 North 6th Avenue

**Remarks:**

Garage.

**Block No. 39**

**Building No. 2**

**ROLL NO. 5**

**NEGATIVE NO. 21**