



ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SURVEY ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY

	1	2	3
<input type="checkbox"/> Unaltered	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Minor Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Major Alteration	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Additions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1: first floor; 2: upper floors; 3: roof/cornice

ARCHITECTURAL SIGNIFICANCE

☐ Significant

☒ Contributing

☐ Non-Contributing

BUILDING CONDITION

☒ Excellent: Well-maintained

☐ Good: Minor maintenance needed

☐ Fair: Major repairs needed

☐ Poor: Deteriorated

ARCHITECTURAL DESCRIPTION

Style: N/A

Date of Construction: ca. 1920

Source: Celebrating History

Features: Baker Memorial Park

Original site of the Penny Brickyard. A gazebo which existed in the 1920's has been removed.



Address:

Baker Memorial Park
Main Street at Fifth Avenue

Representation in Existing Surveys:

☐ Federal

☐ State

☐ County

☐ Local

Block No. 44

Building No. 1

SURVEY DATE:
MAY 1994

ROLL NO. 10

NEGATIVE NO. 33




ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SURVEY ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

CONTINUATION SHEET NO: 1



ROLL NO. 17

NEGATIVE NO. 35

Address:

Baker Memorial Park
Main Street at Fifth Avenue

Remarks:

USGS Marker

Block No. 44

Building No. 1

Address:

Remarks:

Block No.

Building No.

ROLL NO.

NEGATIVE NO.



ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SURVEY ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY

	1	2	3
<input checked="" type="checkbox"/> Unaltered	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Minor Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Major Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Additions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1: first floor; 2: upper floors; 3: roof/cornice

ARCHITECTURAL SIGNIFICANCE

☐ Significant

☒ Contributing

☐ Non-Contributing

BUILDING CONDITION

☒ Excellent: Well-maintained

☐ Good: Minor maintenance needed

☐ Fair: Major repairs needed

☐ Poor: Deteriorated

ARCHITECTURAL DESCRIPTION

Style: Open park

Date of Construction: NA

Source: NA

Features: Lincoln Park

Victorian gazebo in center of park built in 1989 copies pavilion at Pottawatomie Park (1892).



Address:

Lincoln Park
Fourth at Main Streets

Representation in Existing Surveys:

☐ Federal

☐ State

☐ County

☐ Local

Block No. 5

Building No. 1

SURVEY DATE:
MAY 1994

ROLL NO. 1

NEGATIVE NO. 22



ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SURVEY
ST. CHARLES CENTRAL DISTRICT
ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

CONTINUATION SHEET NO: 1



ROLL NO. 17

NEGATIVE NO. 2

Address:

Lincoln Park
Fourth at Main Streets

Remarks:

Block No. 5

Building No. 1

Address:

Remarks:

Block No.

Building No.

ROLL NO.

NEGATIVE NO.



ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT

ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY

	1	2	3
<input checked="" type="checkbox"/> Unaltered	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Minor Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Major Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Additions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1: first floor; 2: upper floors; 3: roof/cornice

ARCHITECTURAL SIGNIFICANCE

- ☐ Significant
- ☐ Contributing
- ☒ Non-Contributing

BUILDING CONDITION

- ☒ Excellent: Well-maintained
- ☐ Good: Minor maintenance needed
- ☐ Fair: Major repairs needed
- ☐ Poor: Deteriorated

ARCHITECTURAL DESCRIPTION

Style: Commercial Vernacular

Date of Construction: 1984

Source: Field Observation

Features:

Miniature buildings built for children's "Safety Town".
Gable roofs with plywood and clapboard sidings.

**Address:**

Safety Town Park
First at State Avenues

Representation in Existing Surveys:

- ☐ Federal
- ☐ State
- ☐ County
- ☐ Local

Block No. 29

Building No. 1

SURVEY DATE:

MAY 1994

ROLL NO. 4

NEGATIVE NO. 15