



ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SURVEY ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY

	1	2	3
<input type="checkbox"/> Unaltered	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Minor Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Major Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Additions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insensitive to original	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1: first floor; 2: upper floors; 3: roof/cornice

BUILDING CONDITION

- Excellent: Well-maintained
- Good: Minor maintenance needed
- Fair: Major repairs needed
- Poor: Deteriorated

ARCHITECTURAL DESCRIPTION

Style: National

Date of Construction: 1870-1910

Source: A Field Guide to American Houses

Features:

Two major front gables with gabled entry at front section, full width porch at rear section.

ARCHITECTURAL SIGNIFICANCE

- Significant
- Contributing
- Non-Contributing



Address:

114 South 5th Street

Representation in Existing Surveys:

- Federal
- State
- County
- Local

Block No. 13

Building No. 8

SURVEY DATE:

MAY 1994

ROLL NO. 11

NEGATIVE NO. 22



ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SURVEY
ST. CHARLES CENTRAL DISTRICT
ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

CONTINUATION SHEET NO: 1



Address:

114 South 5th Street

Remarks:

Garage.

Block No. 13

Building No. 8

ROLL NO. 11

NEGATIVE NO. 23



Address:

114 South 5th Street

Remarks:

Garage.

Block No. 13

Building No. 8

ROLL NO. 11

NEGATIVE NO. 21



ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SURVEY
ST. CHARLES CENTRAL DISTRICT
ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY

	1	2	3
<input checked="" type="checkbox"/> Unaltered	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Minor Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Major Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Additions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1: first floor; 2: upper floors; 3: roof/cornice

ARCHITECTURAL SIGNIFICANCE

Significant

Contributing

Non-Contributing

BUILDING CONDITION

Excellent: Well-maintained

Good: Minor maintenance needed

Fair: Major repairs needed

Poor: Deteriorated

ARCHITECTURAL DESCRIPTION

Style: Prairie

Date of Construction: 1900-1920

Source: A Field Guide to American Houses

Features:

Hipped roof, symmetrical with full width front entry porch, dormer at roof, two story structure. Shingle texture at second floor walls, wood clapboard at first floor. Rock face block foundation.



Address:

122 South 5th Street

Representation in Existing Surveys:

Federal

State

County

Local

Block No. 13

Building No. 7

SURVEY DATE:

MAY 1994

ROLL NO. 11

NEGATIVE NO. 20



ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SURVEY
ST. CHARLES CENTRAL DISTRICT
ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

CONTINUATION SHEET NO: 1



Address:

122 South 5th Street

Remarks:

South Elevation.

Block No. 13

Building No. 7

ROLL NO. 2

NEGATIVE NO. 32

Address:

Remarks:

Block No.

Building No.

ROLL NO.

NEGATIVE NO.



ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SURVEY
ST. CHARLES CENTRAL DISTRICT
ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY

	1	2	3
<input type="checkbox"/> Unaltered	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input checked="" type="checkbox"/> Minor Alteration	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Major Alteration	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/> Additions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Sensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Insensitive to original	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

1: first floor; 2: upper floors; 3: roof/cornice

ARCHITECTURAL SIGNIFICANCE

Significant

Contributing

Non-Contributing

BUILDING CONDITION

Excellent: Well-maintained

Good: Minor maintenance needed

Fair: Major repairs needed

Poor: Deteriorated

ARCHITECTURAL DESCRIPTION

Style: Vernacular Late Victorian

Date of Construction: 1911

Source: Reflections of St. Charles

Features:

Shelby School is now used as offices. Masonry building of red brick and stone accents. Parapet is capped with decorative stone embellished with date carved in front. Some windows have been filled in with plywood. Heavy stone surround at entrance.



Address:

210 South Fifth Street

Representation in Existing Surveys:

Federal

State

County

Local

Block No. 17

Building No. 3

SURVEY DATE:

MAY 1994

ROLL NO. 11

NEGATIVE NO. 16



ST. CHARLES HISTORIC PRESERVATION COMMISSION

ARCHITECTURAL SURVEY
ST. CHARLES CENTRAL DISTRICT
ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

CONTINUATION SHEET NO: 1



Address:

210 South Fifth Street

Remarks:

North Elevation

Block No. 17

Building No. 3

ROLL NO. 11

NEGATIVE NO. 17



Address:

210 South Fifth Street

Remarks:

South Elevation

Block No. 17

Building No. 3

ROLL NO. 2

NEGATIVE NO. 33