

HISTORIC PRESERVATION COMMISSION			
AGENDA ITEM EXECUTIVE SUMMARY			

Agenda Item
Title/Address: COA: 117 N 5<sup>th</sup> Ave

**Significance:** Contributing

**Petitioner:** Frank Florizoone

**Project Type:** Windows

PUBLIC HEARING

MEETING
9/16/20

X

### **Agenda Item Category:**

	Preliminary Review		Grant
X	Certificate of Appropriateness (COA)		Other Commission Business
	Landmark/District Designation		Commission Business
477 1 175			141 ID 4 ID 4

## Attached Documents:Additional Requested Documents:Application, Design Drawings, PhotosNone

### **Project Description:**

Replace the two front storm windows and front storm door. The windows and door will be replaced with the following:

- Larson® Better Series White Exterior Storm Window with Low-E Glass
- Larson® Cedar 36" x 80" White Highview Storm Door
- Larson® White Finish Aluminum Fixed Sidelites Storm Panel

Link to windows: <a href="https://www.menards.com/main/doors-windows-millwork/windows/storm-windows/larson-reg-better-series-white-exterior-storm-window-with-low-e-glass/l20132439es/p-1537424884600.htm">https://www.menards.com/main/doors-windows-millwork/windows/storm-windows-larson-reg-better-series-white-exterior-storm-window-with-low-e-glass/l20132439es/p-1537424884600.htm</a>

### **Staff Comments:**

### **Recommendation / Suggested Action:**

Provide feedback and recommendation on approval of the COA

### **APPLICATION FOR COA REVIEW**

### HISTORIC PRESERVATION "CERTIFICATE OF APPROPRIATENESS"



(630) 377-4443 COMMUNITY & ECONOMIC DEVELOPMENT DEPARTMENT / CITY OF ST. CHARLES To be filled out by City Staff Date Submitted: 9 / 14 / 2020 COA# Admin. Approval: Permit #: **APPLICATION INFORMATION** Address of Property: Use of Property: ☐Commercial, business name: □ Residential □Other: **Project Type:** □ Demolition ☑ Exterior Alteration/Repair ☐Primary Structure ☐ New Construction **WWindows** ☐Garage/Outbuilding ☐Primary Structure **☑**Doors □ Additions Other\_ ☐Siding - Type: □Deck/Porch ☐Masonry Repair ☐ Relocation of Building ☐Garage/Outbuilding ☐ Other ☐ Awnings/Signs Other Description: orch storm windows with Like-for-Like **Applicant Information:** Applicant is (check all that apply): Name (print): Property Owner Address: ☐ Business Tenant ☑ Project contractor Phone: ☐ Architect/Designer Email: Property Owner Information (if not the Applicant) Name (print): Address: Signature: APPLICANT/AUTHORIZED AGENT SIGNATURE

I agree that all work shall be in accordance with the plans, specifications and conditions which accompany this application, and I have read and understand the Historic Preservation COA General Conditions.

Signature:	Thurson .	Date: Sep 12, 20 20
- 9		

# 117, 5<sup>TH</sup> AVE, ST. CHARLES, IL 60174 PROPOSED WORKS – Storm windows

Storm windows: the original plan was to remove the old storm-windows which were broken and in bad condition. However, after removing the old storm-windows, we realized that there is lots of caulk and paint between the bricks and wooden frame on which they are mounted. This will be nearly impossible to clean-up correctly if the wooden frames are removed and will look ugly.

Also leaving the wooden frames on their own will look odd.

And we noticed quite a bit of rain coming in the porch, making the area not very useable.

Therefore, we propose to replace the old storm windows with like-for-like.



### Proposed replacement

Larson® Better Series White Exterior Storm Window with Low-E Glass Larson® Cedar 36" x 80" White Highview Storm Door Larson® White Finish Aluminum Fixed Sidelites Storm Panel





### Specifications

Collection	Better Series	Material	Aluminum
Mounting Method	Inside Mount (Blindstop), Outside Mount (Overlap	Color/Finish	White
Energy Star Zone	Northern, North-Central	Product Type	Exterior Storm Windows
Frame Width	24 inch	Frame Height	39 inch
Glazing Type	Low-E, Single Pane	Screen Material	Fiberglass Mesh
Screen Color	Charcoal	Manufacturer Warranty	10 year
View Return Policy			



### ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY			BUILDING CONDITION	
	1	2	3	⊠ Excellent: Well-maintained
☑ Unaltered				☐ Good: Minor maintenance needed
☐ Minor Alteration				☐ Fair: Major repairs needed
☐ Major Alteration				☐ Poor: Deteriorated
□ Additions □ □   Sensitive to original □ □   Insensitive to original □ □   1: first floor; 2: upper floors; 3: roof/cornice    ARCHITECTURAL SIGNIFICANCE  □ Significant □ Contributing □ Non-Contributing			ARCHITECTURAL DESCRIPTION  Style: Craftsman  Date of Construction: 1905-1930  Source: A Field Guide to American Houses  Features:  One story brick structure with hipped roof and dormers, often referred to as the Bungaloid style. Large overhanging eave is enclosed. Totally enclosed front porch. Paired windows at porch	



ROLL NO. 5

**NEGATIVE NO. 30** 

#### Address:

117 North 5th Avenue

### Representation in Existing Surveys:

- ☐ Federal
- ☐ State
- ☐ County
- ☐ Local

Block No. 38

**Building No. 6** 

**SURVEY DATE:** 

**MAY 1994**