	A - 200					ATION COMMISSION ECUTIVE SUMMARY	
		Agenda Item Title/Address:	COA: 2	15 N	3 <sup>rd</sup> A	Ave.	
		Significance:	Contribu	ting/ L	andn	narked	
	RK	Petitioner:	Elizabeth	suwa	nski		
	CITY OF	Project Type:	Windows	6			
	CHARLES	PUBLIC HEAD	RING			MEETING 6/3/20	X
Age	nda Item Ca	itegory:					
	Preliminary R	leview			Gra	nt	
X	Certificate of	Appropriateness (CC	DA)		Oth	er Commission Business	
	Landmark/Dis	strict Designation			Con	nmission Business	
Atta	ched Docun	nents:		Add	itio	nal Requested Documents:	
	ication, Curren itectural Surve	t photos, photos,		None	<b>;</b>		
Pro	ject Descript	ion:					
• • Staf	•	idows will be alumin				r of the west side of house. e design of the current windows.	
Staf	T Comments	•					

**Recommendation / Suggested Action:** 

• Provide feedback and recommendation on approval of the COA

## **APPLICATION FOR COA REVIEW**

HISTORIC PRESERVATION "CERTIFICATE OF APPROPRIATENESS"

COMMUNITY & ECONOMIC DE	EVELOPMENT DEPARTMENT / CITY OF ST. CHARLES	(630) 377-4443	ST. CHARLES
To be filled out by City Staff			
Permit #:	Date Submitted: <u>5 / 28 / 2020</u> COA #	Admin. Approval:	
APPLICATION INFORMA	ATION		
Address of Property:	215 N 3rd Ave		
Use of Property:	Commercial, business name:		
	Residential     Other:		
Project Type:			
☐ Exterior Alteration ↓ Windows ↓ Doors ↓ Siding - Type: ↓ Masonry Repart ↓ Other ↓ Awnings/Signs	New Construction     Primary Structure     Additions air	<ul> <li>Demolition</li> <li>Primary Structure</li> <li>Garage/Outbuilding</li> <li>Other</li> <li>Relocation of Building</li> </ul>	

#### Description:

Back windows of the house are not original and are ill-fitting, causing cold and hot air to pour into the room, which makes it hard to maintain a comfortable temperature. We would like to replace with them with wood clad vinyl windows. Most of the rest of the windows are original and will be restored in time but these are not so we would like to replace.

Applicant Information:	
Elizabeth Suwapaki	Applicant is (shack all that apply):

Name (print):		Applicant is (check all that apply).
Address:	215 N 3rd Avw	Property Owner
Phone:	7734207362	Project contractor     Architect/Designer
Email:	elizabethsuwanski@yahoo.com	
Property Owner Informat	ion (if not the Applicant)	
Name (print):		
Address:		
Signature:		

### **APPLICANT/AUTHORIZED AGENT SIGNATURE**

I agree that all work shall be in accordance with the plans, specifications and conditions which accompany this application, and I have read and understand the Historic Preservation COA General Conditions.

Signature:

Date: 5/28/2020

Windows we are proposing:



## DOUBLE HUNG

Our double hung wood-clad vinyl windows bring comfort and beauty with interior stain or paint.

Neopor<sup>®</sup> insulation

#### Aeris Double Hung Standard Features

- Premium Oak, Cherry or
  - Maple hardwood interior Dual weatherstripping
- 3¼" frame depth
- Proprietary European sweep locks and tilt latches formulation vinyl (Windows less than 24"
- Welded frame and sash construction
- balance system for a quiet fiberglass mask (0) (UtraVue® balance system may be some filter and the some filter an may be required for extremely large or small Jamb pocket color window sizes)
- Interior glazing
- options
- Wood lift at lock rail
- It ComforTech™ DLA-UV
   Ave a single passive
   DualTech sweep lock and low profile tilt latches) Compound Tension™
   Extruded aluminum full

Two integrated DualTech™


- fiberglass mesh (Screen
- coordinates with stain and paint colors
- See price list for additional

There will not be the grids inside the glass - they will be clear glass to match the rest of the one over one double hung windows.

Current inside view (don't mind my kids' art work):



Outside view from the street (Chestnut Ave). Windows face the driveway, not the street:





# ARCHITECTURAL SURVEY ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

## DIXON ASSOCIATES / ARCHITECTS

1 2 3   □ Unaltered □   □ Major Alteration □   □ Major Alteration □   □ Additions □   □ Additions □   □ Sensitive to original □   □ Insensitive to original □   □ I: first floor; 2: upper floors; 3: roof/cornice     ARCHITECTURAL DESCRIPTION   Style: Queen Anne   Date of Construction:   1880-1910   Source: A Field Guide to American Houses   Fatures:   Stepip pitched roof of irregular shapes with dominant front facing gable, shingle texture.     Significant   © Contributing   □ Non-Contributing     Non-Contributing     Contributing     Non-Contributing     Roll NO. 15     NEGATIVE NO. 14     Address:   215 North 3rd Avenue     State   □ County   □ Local	ARCHITECTURAL	INTE	GRI	ТҮ	BUILDING CONDITION
□ Minor Alteration       □         □ Major Alteration       □         □ Additions       □         □ Additions       □         □ Sensitive to original       □         □ Insensitive to original       □         □ I: first floor; 2: upper floors; 3: roof/comice       ARCHITECTURAL DESCRIPTION         Significant       □         □ Contributing       □         □ Non-Contributing       □         □ Country       □         □ Country       □         □ Disclose       □         □ State       □         □ County       □         □ Disclose       □         □ Disclose       □         □ Disclose       □		1	2	3	Excellent: Well-maintained
□ Major Alteration       □         □ Additions       □         □ Additions       □         □ Sensitive to original       □         □ Insensitive to original       □         □ Isensitive to original       □         □ State       □         □ County       □         □ Isensitive to original       □         □ Isensitive to original       □         □ Isensitive to original       □         □ Isensitive to original	Unaltered				☐ Good: Minor maintenance needed
Additions	⊠ Minor Alteration	$\boxtimes$			Fair: Major repairs needed
Additions   Sensitive to original   Insensitive to original   Insensitive to original   Insensitive to original   I: first floor; 2: upper floors; 3: roof/cornice   ARCHITECTURAL SIGNIFICANCE   Significant   Contributing   Non-Contributing   Address:   215 North 3rd Avenue     Representation in   Existing Surveys:   Pederal   State   County   Istate   County   Incensition   State   County   Istate   County   Istate   State   County   Istate   State   County   Istate   State	☐ Major Alteration				Poor: Deteriorated
215 North 3rd Avenue         215 North 3rd Avenue         Representation in         Existing Surveys:         Federal         State         County         Local         Block No. 30         Building No. 1         SURVEY DATE:	Sensitive to origina Insensitive to origina 1: first floor; 2: upper floor ARCHITECTURAL SIG	l□ rs; 3: roc	D f/corni	Ce	Style: Queen AnneDate of Construction:1880-1910Source: A Field Guide to American HousesFeatures:Steeply pitched roof of irregular shapes with dominant
EF. NO. 250				A State of the sta	215 North 3rd Avenue         Representation in Existing Surveys:         Federal         State         County         Local         Block No. 30 Building No. 1         SURVEY DATE: