HISTORIC PRESERVATION COMMISSION AGENDA ITEM EXECUTIVE SUMMARY **Agenda Item** PR: 107-109 Main Street (George's Sport Building) Title/Address: Consideration of Renovation or Demolition **Proposal: Petitioner:** Peter Suhr, City of St. Charles Director of Public Works SINCE 1834 Please check appropriate box (x) **PUBLIC HEARING MEETING** \mathbf{X} 2/15/17 **AGENDA ITEM CATEGORY:** Certificate of Appropriateness (COA) Façade Improvement Plan X **Preliminary Review** Landmark/District Designation Discussion Item **Commission Business ATTACHMENTS:** None

EXECUTIVE SUMMARY:

The City purchased the property at 107-109 Main Street otherwise known as the former George's Sport Building in 2012 with intent to utilize the building or land as a compliment to the adjacent Arcada Theatre. In 2012, the building was in fair condition, however has slowly continued to deteriorate over time. The Public Works Department is responsible for the care and maintenance of City owned buildings including George's Sport. Recognizing the continued deteriorating conditions of the building, Public Works recently retained Prairie Forge Architects to evaluate the structure and determine solutions including cost estimates for improvements. Public Works, with assistance from Prairie Forge, has concluded its study and is prepared to present two options to our City Council for their consideration. The first option is to renovate the exterior of the building to provide for a weather tight solution. The second option is to demolish the building in its entirety and construct a temporary City Plaza in its place until the property is redeveloped.

More detailed information will be presented to you at the Commission Meeting. City staff is interested to receive your feedback before the proposals are offered to the Government Services Committee.

RECOMMENDATION / SUGGESTED ACTION:

Provide feedback and recommendations on proposed solutions.



ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

DIXON ASSOCIATES / ARCHITECTS

ARCHITECTURAL INTEGRITY				BUILDING CONDITION
	1	2	3	☐ Excellent: Well-maintained
□ Unaltered				☐ Good: Minor maintenance needed
☐ Minor Alteration	\boxtimes			☐ Fair: Major repairs needed
☐ Major Alteration				☐ Poor: Deteriorated
□ Additions Sensitive to original Insensitive to original 1: first floor; 2: upper floors; ARCHITECTURAL SIGN □ Significant □ Contributing □ Non-Contributing	3: roo			ARCHITECTURAL DESCRIPTION Style: Commercial Vernacular Date of Construction: 1900-1920 Source: Field Observation Features: Two-story masonry structure, brick with stone banding at second floor window heads. Two bay windows with stamped metal ornamentation.



ROLL NO. 7

NEGATIVE NO. 33

Address:

107-109 East Main Street

Representation in Existing Surveys:

- ☐ Federal
- ☐ State
- ☐ County
- ☐ Local

Block No. 47

Building No. 6

SURVEY DATE:

MAY 1994

107-109 E Main St.

