

TREE REPORT TOTALS DECEMBER 2023

TRIMMING - 130

REMOVALS - 28

EMERGENCY REMOVALS - 0

TREE REMOVAL DATA

WORK	QUAD	SPECIES	DBH	NOTES
In-House Removal	NW	Ash, White	10	condition
In-House Removal	SW	Mulberry	50	storm damage
In-House Removal	NW	Cypress, Bald	5	condition
In-House Removal	SW	Pear, Callery	23	condition
In-House Removal	NE	Ash, Green	12	EAB
In-House Removal	NE	Ash, Royal Purple	10	EAB
In-House Removal	NE	Ash, Black	14	EAB
Third-Party Removal	SE	Apple, Common	13	condition, removed privately
In-House Removal	NE	Apple, Common	26	condition
In-House Removal	NE	Apple, Common	26	condition
Contract Removal	SE	Linden, Basswood	23	rot/decay
Contract Removal	SE	Maple, Crimson King	23	multiple cracks in main trunk
Contract Removal	SE	Elm, Siberian	37	weak branch unions, spitting bark
Contract Removal	SE	Maple, Boxelder	25	rot/decay
Contract Removal	SE	Maple, Crimson King	10	storm damage
Contract Removal	SE	Locust, Thornless Shademaster	24	> 50% crown loss
Contract Removal	SW	Maple, Norway	32	rot/decay
Contract Removal	SW	Maple, Norway	33	storm damage
Contract Removal	SW	Elm, Vanguard	14	damage due to vehicle accident
Contract Removal	SW	Maple, Silver	25	rot/decay
Contract Removal	SW	Linden, Basswood	30	canopy 40% dead, dangerous limbs over street
Contract Removal	SW	Maple, Norway	26	rot/decay
Contract Removal	SW	Maple, Norway	21	rot/decay
Contract Removal	NE	Locust, Thornless Shademaster	27	canopy ~ 100% dead
Contract Removal	NE	Maple, Norway	17	rot/decay
Contract Removal	SW	Elm, Siberian	33	> 80% dead
Contract Removal	SW	Elm, Siberian	27	> 80% dead
Contract Removal	SW	Elm, American	42	condition