# HISTORIC PRESERVATION COMMISSION AGENDA ITEM EXECUTIVE SUMMARY **Agenda Item** COA: 213 S. 3<sup>rd</sup> St. Title/Address: **Proposal:** Replace siding **Petitioner:** Dave Saelens SINCE 1834 Please check appropriate box (x) **PUBLIC HEARING MEETING** $\mathbf{X}$ 6/5/13 **AGENDA ITEM CATEGORY:** X Certificate of Appropriateness (COA) Façade Improvement Plan **Preliminary Review** Landmark/District Designation Discussion Item **Commission Business ATTACHMENTS:** Information on replacement window Photos of the building showing replacement window installed

#### **EXECUTIVE SUMMARY:**

On 5/15/13, the Commission provided preliminary review comments on a proposal to replace siding on the building at 213 S. 3<sup>rd</sup> St. The conceptual proposal is to replace the siding with fiber cement siding to match the existing architecture and details. No window trim or windows would be replaced.

The Commission requested a site visit to view the condition of the siding. The site visit will be conducted at 6:00pm. The Commission will discuss the findings at the meeting.

The item has been listed for a COA approval, in the event the Commission has sufficient information to vote on a COA.

## **RECOMMENDATION / SUGGESTED ACTION:**

Provide feedback and recommendations for approval of the COA.



# ARCHITECTURAL SURVEY

CENTRAL HISTORIC DISTRICT ST. CHARLES, ILLINOIS

#### ST. CHARLES HISTORIC PRESERVATION COMMISSION

**Primary Structure** 

ADDRESS 213 S 3rd St

1994 Photo Roll: 3 Negative: 28



Photo: Aug. 2003

# **ARCHITECTURAL SIGNIFICANCE**

- ♦ Significant
- □ Contributing
- □ Non-Contributing
- ☐ Potential for Individual National Register Designation

### **BUILDING CONDITION**

- ♦ Excellent
- □ Good
- □ Fair
- Poor

### ARCHITECTURAL INFORMATION

| Architectural Style/Type:   | Shingle   | Exterior Walls (Current):  | Clapboard     |
|-----------------------------|-----------|----------------------------|---------------|
| Architectural Features:     |           | Exterior Walls (Original): | Clapboard     |
| Date of Construction:       | 1880-1900 | Foundation:                | Stone         |
| Source:                     |           | Roof Type/Material:        | Gable/Asphalt |
| Overall Plan Configuration: |           | Window Material/Type:      |               |

**ARCHITECTURAL FEATURES:** Cross gabled roof building with shingle texture in gables, notched over windows at second floor. Large expanse of glass at first floor at front. Wood clapboard at first floor on stone foundation. Porches on east and south sides.

**ALTERATIONS:** None