HISTORIC PRESERVATION COMMISSION AGENDA ITEM EXECUTIVE SUMMARY Agenda Item COA: 213 S. 3rd St. Title/Address: Proposal: Façade Grant to replace siding **Petitioner:** Dave Saelens SINCE 1834 Please check appropriate box (x) **PUBLIC HEARING MEETING** X 10/16/13 **AGENDA ITEM CATEGORY:** X Certificate of Appropriateness (COA) X Façade Improvement Plan **Preliminary Review** Landmark/District Designation Discussion Item **Commission Business ATTACHMENTS:** Application and proposal Minutes from 6/5/13 Commission discussion Architectural Survey **EXECUTIVE SUMMARY:** The owner has requested a Façade Improvement Grant to assist with funding the removal and

replacement of siding on the building. The proposal includes use of either cedar or hardie board.

The Commission held a site visit to view the siding and discuss their observations at the meeting on 6/5/13. The meeting minutes are attached.

A Façade Improvement Grant could fund maximum of \$8,000 based on the frontage of the building (24 feet).

The owner and contractor will be in attendance to answer questions and provide additional information.

RECOMMENDATION / SUGGESTED ACTION:

Provide feedback and recommendations for approval of the COA.

RECEIVED St. Charles, IL Received _____

OCT 0 7 2013

CITY OF ST. CHARLES FACADE IMPROVEMENT PROGRAM APPLICATION FORM

CDD Planning Division

A non-refundable fee of \$50.00 must accompany this application. Checks should be made payable to the City of St. Charles.

1) Applicant: DAVID L. SA	10,518	
1) Applicant: $DHV/D L$. f	(Name)	
Home Address: 2/3 S. 3/4 (Street)		<u> 74</u>
Business Address: SAME (Street)		
(Street)	(City/State/Zip)	(Phone)
Federal Tax ID Number:		
2) Building or establishment for which the re	imhursement grant is squaht	
213 S. 3º ST STCHARLE	SAL 601 M	
09	<u>-34-113-005.000</u>	
(Prop	perty Identification Number)	
4) Is this property listed on the National Regions 3) Proposed Improvements (Check all that appropriate the second		:□Yes ⊠No
ズ Canopy/Awning	□ Signage	
☐ Windows/Doors	☐ Exterior Lighting	
☐ Tuck pointing/Masonry Repair		
☐ Masonry Cleaning ☐ Painting	☐ Rear Entrance Improvements(Pleas	se specify below)
MI Othory Diogra Consider > // ////		
☑ Other(Please Specify) S/D/NQ		
Describe the scope and purpose of the work t		
Describe the scope and purpose of the work to REMOVE + REPLACE S		
Describe the scope and purpose of the work t		
Describe the scope and purpose of the work t		

4) S	tatement of Understanding:
A.	I agree to comply with the guidelines and procedures of the St. Charles Façade Improvement Program.
B.	I understand that I must submit detailed cost documentation, copies of bids, contracts, invoices, receipts, and contractor's final waivers of lien upon completion of the approved improvements.
C.	I understand that work done before a Façade Improvement Agreement is approved by the City Council is not eligible for a grant.
D.	I understand the Façade Improvement reimbursement grants are subject to taxation and that the City is required to report the amount and recipient of said grants to the IRS
	Signature Dan J Syulus Applicant
Ifth	e applicant is other than the owner, you must have the owner complete the following certificate:
8	certify that I am the owner of the property at, and that I authorize the applicant to apply for a reimbursement grant under the St. Charles Facade Improvement Program and undertake the approved improvements.

Date

Signature_

Owner



HOME IMPROVEMENT AGREEMENT

NAME: 1500 Saelens	(Owner)
ADDRESS: 2/3 5 3 1 5+ DATE:	
CITY: 5+ Charles STATE: ZL ZIP CODE: 60	174
PHONE: ALT PHONE:	
The undersigned Seller agrees to furnish the following materials, improvements, labor, and	or services:
Hurdie - Belly Bund, CorNels Post. 4Duch Straig	H+ Chile
	-v, Spione
No Charge for Kotter wood = Capping of	all WiW Dows.
- To see the second of the sec	2001 0010 00001.
	
Celul work (Cedul	191-00
1990 / 1900 / 19	0 1 -00
101001	
77000,00/	(N), (12)
) 00 , 0 - \
40% Nows 60% rupes completion	
This contract is all install all above products. 100% Lifetime parts and labor warranty on applicable products This contract is all inclusive any changes may involve an extra cost and are to be in writing a signed by both the sells this job to start approximately have a commencement date") to be completed approximately these dates are approximations and may vary slightly. Total Sale Price of work to be performed \$ Today \$	Deposit The Ady S Deposit Syment of CVV CONTAINED HEREIN CHIS AGREEMENT AND WITH WORK T OF A COPY OF THE
GRSW BY: OWNER'S APPROVAL (BUY) Approval: OWNER SIGNATURE	ER)
AUTHORIZED REPRESENTATIVE OWNER SIGNATURE	
OWNER SIGNATURE	

PLAT OF SURVEY


DALE A. FLOYD

9N544 ARROWMAKER PASS ELGIN, IL 60123 PHONE: 847-742-7691

THE NORTHERLY HALF OF LOT 7 (EXCEPT THE WESTERLY 63.0 FEET OF THE SOUTHERLY 33.0 FEET THEREOF) AND THE NORTHERLY HALF OF LOT 8, ALL IN BLOCK 51 OF THE ORIGINAL TOWN OF ST. CHARLES, IN THE CITY OF ST. CHARLES, KANE COUNTY, ILLINOIS.

COMMONLY KNOWN AS: 213 SO. THIRD STREET, ST. CHARLES, ILLINOIS.

THIS SURVEY WAS
PREPARED FOR A REAL ESTATE
CLOSING AND IS TO BE
USED FOR NO OTHER PURPOSE.



State of Illinois

S.S.

County of Kane

SCALE: 1" =20' NOTE: Survey not valid without embossed seal.

I, DALE A. FLOYD, Do hereby certify that the above described property has been surveyed under my supervision in the manner represented on the plat

Historic Preservation Commission Minutes – June 5, 2013 Page 2

made to replace the roof. He said he understood that if the window did not match the style of the building, they would agree to replace the window to match the original.

The Commission discussed that lannon stone could be stained if there was an interest in changing the color.

Chairman Smunt said that as a future project, the Commission discussed obtaining the services of an architect to redesign the front elevation using pairs of double hung windows. He said based on past discussion with the Commission, there was not support for allowing the replacement window, as the Commission felt the window design and material choice was not appropriate for the building.

5. COA: 213 S. 3rd St.

Prior to the meeting, Chairman Smunt, Mr. Norris and Mr. Colby attended a site visit at 213 S. 3rd St. with Dave Saelens, building owner, to review the condition of the siding proposed for replacement.

Chairman Smunt noted that the condition of the siding and wood shingles varies by elevation. The worst condition is on the south elevation, where due to shingle splits, over 50% is deteriorated, in which case the entire elevation of shingle would need to be replaced. On the north elevation, there was less deterioration, with maybe 30% requiring replacement. He noted that once you begin the work of replacing individual shingles, more shingle will be damaged and require replacement, and at some point, the mix of new and old shingle will look bad.

Mr. Norris stated that in his opinion, the major issue is ventilation through the siding. A lot of the visible damage could be corrected with a proper priming and painting and taking measures to ensure the humidity is venting out of the walls and attic.

Chairman Smunt stated Mr. Saelens had obtained quotes for fiber cement and cedar that were very high. Based on the site visit, he suggested obtaining quotes for a repair and partial replacement with like materials, along with a proper painting. Mr. Withey suggested contacting Mr. Prestidge for a recommendation for an independent carpenter who can perform the work.

The Commission discussed that the property may be eligible for a Façade Improvement Grant, but the property is outside of SSA 1-B and therefore is second priority for funding. Mr. Colby said he would check the status of the current grant applications and see what is available. There was no specific COA request for the Commission to consider. Mr. Saelens will obtain additional quotes and follow up.



ARCHITECTURAL SURVEY

CENTRAL HISTORIC DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

Primary Structure

ADDRESS 213 S 3rd St

1994 Photo Roll: 3 Negative: 28



ARCHITECTURAL SIGNIFICANCE

- ♦ Significant
- ☐ Contributing
- □ Non-Contributing
- □ Potential for Individual National Register Designation

BUILDING CONDITION

- Excellent
- □ Good
- □ Fair
- □ Poor

ARCHITECTURAL INFORMATION

Architectural Style/Type:	Shingle	Exterior Walls (Current):	Clapboard
Architectural Features:		Exterior Walls (Original):	Clapboard
Date of Construction: Source:	1880-1900	Foundation: Roof Type/Material:	Stone Gable/Asphalt
Overall Plan Configuration:		Window Material/Type:	

ARCHITECTURAL FEATURES: Cross gabled roof building with shingle texture in gables, notched over windows at second floor. Large expanse of glass at first floor at front. Wood clapboard at first floor on stone foundation. Porches on east and south sides.

ALTERATIONS: None