
| ST. CHARLES<br>SINCE 1834 |                | HISTORIC PRESERVATION COMMISSION AGENDA ITEM EXECUTIVE SUMMARY |   |                              |                     |  |   |  |  |  |
|---------------------------|----------------|--|---|------------------------------|---------------------|--|---|--|--|--|
|                           |                | Agenda Item<br>Title/Address:                                  | Discussion (Police Sta                            |                              | 211                 | N. Riverside Ave.  |   |  |  |  |
|                           |                | Proposal:  | Background  | ackground for facility study |                     |  |   |  |  |  |
|                           |                | Petitioner:  | Raymond Lee, FGM Architects / City of St. Charles |                              |                     |  |   |  |  |  |
|                           |                | Please check appropriate box (x)                               |   |                              |                     |  |   |  |  |  |
|                           |                | PUBLIC HI  | PUBLIC HEARING                                    |                              |                     | MEETING<br>3/4/15  | X |  |  |  |
| AGI                       | ENDA ITEM      | CATEGORY:  |   |                              |                     |  |   |  |  |  |
|                           | Certificate of | of Appropriateness   | (COA)   | Façade Improvement Plan      |                     |  |   |  |  |  |
|                           | Preliminary    | eliminary Review   |   |                              |                     | Landmark/District Designation                                  |   |  |  |  |
| X                         | Discussion     | n Item   |   |                              | Commission Business |  |   |  |  |  |
| ATT                       | CACHMENT       | S:   |   | <b>!</b>                     |                     |  |   |  |  |  |
| Ques                      | stions from FO | GM Architects for  | facility study                                    |                              |                     |  |   |  |  |  |
| Arch                      | itectural Surv | ey pages   |   |                              |                     |  |   |  |  |  |
| EXE                       | ECUTIVE SU     | MMARY:   |   |                              |                     |  |   |  |  |  |
| Depa                      | artment, which | h includes an asses  | sment of the co                                   | urrent fa                    | acili               | ility study for the St. Charles Polty at 211 N. Riverside Ave. |   |  |  |  |
| They                      | are seeking i  | input from the Com   | ımission regar                                    | ding the                     | pro                 | pperty.  |   |  |  |  |

RECOMMENDATION / SUGGESTED ACTION:

Provide feedback and recommendations.









#### **CITY OF ST. CHARLES**

#### POLICE STATION SPACE NEEDS STUDY

#### Request for Historical Preservation Commission Meeting

FGM Architects beginning a study on how to improve the working conditions of the Police Department and is requesting a meeting with the Historical Preservation Commission meeting to understand if there is any historical significance of the current Police Station and adjacent properties.

The following are questions we would like to discuss with the Commission.

- 1. Is there any historical significance to the current police station?
- 2. Can the Commission provide us with the background history of the property relative to the river and Downtown Business District?
- 3. What are the historical implications if the Police Station was modified with an addition?
- 4. What are the implications if the City chooses to tear down and replace the Police Station on the existing property?
- 5. What are the Commission's goals for restoring/redeveloping properties in the Downtown Business District?




# ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

DIXON ASSOCIATES / ARCHITECTS

| ARCHITECTURAL IN  | NTE  | GRI                | BUILDING CONDITION |  |  |  |
|---|------|--------------------|--------------------|--|--|--|
|   | 1    | 2                  | 3                  | ☐ Excellent: Well-maintained   |  |  |
| <b>☑</b> Unaltered  |      |                    |                    | ☐ Good: Minor maintenance needed   |  |  |
| ☐ Minor Alteration  |      |                    |                    | ☐ Fair: Major repairs needed   |  |  |
| ☐ Major Alteration  |      |                    |                    | ☐ Poor: Deteriorated   |  |  |
| ☐ Additions  Sensitive to original  Insensitive to original  1: first floor; 2: upper floors; |      | □ □ □ □ □ f/cornic |                    | ARCHITECTURAL DESCRIPTION  Style: Modern  Date of Construction: 1985  Source: Field Observation  Features:  One story aggregate finish exterior with metal hip roof. |  |  |
| ARCHITECTURAL SIGN  | IFIC | CANC               | E                  | Large overhanging eaves with horizontal emphasis in lines of roof.   |  |  |
| ☐ Significant   |      |                    |                    |  |  |  |
| ☐ Contributing  |      |                    |                    |  |  |  |
| Non-Contributing     ■  |      |                    |                    |  |  |  |






# ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

DIXON ASSOCIATES / ARCHITECTS

| ARCHITECTURAL IN  | NTE         | GRI                                   | BUILDING CONDITION |   |  |
|---|-------------|---------------------------------------|--------------------|---|--|
|   | 1           | 2                                     | 3                  | ☐ Excellent: Well-maintained  |  |
| ☐ Unaltered   |             |                                       |                    | ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐   |  |
| ☐ Minor Alteration  |             |                                       |                    | ☐ Fair: Major repairs needed  |  |
|   |             | $\boxtimes$                           |                    | ☐ Poor: Deteriorated  |  |
| Additions  Sensitive to original  Insensitive to original  1: first floor; 2: upper floors; | $\boxtimes$ | □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ |                    | ARCHITECTURAL DESCRIPTION  Style: Substantially altered  Date of Construction: Pre 1900  Source: A Field Guide to American Architecture  Features:  |  |
| ARCHITECTURAL SIGN  | IFIC        | CANC                                  | E                  | Original factory building at east side, addition to west.  South face clad with limestone slabs in 1930's. East facade shows band of face brick as decorative element in common brick wall. |  |
| ☐ Contributing  |             |                                       |                    |   |  |
| ⊠ Non-Contributing  |             |                                       |                    |   |  |





# ARCHITECTURAL SURVEY

ST. CHARLES CENTRAL DISTRICT ST. CHARLES, ILLINOIS

DIXON ASSOCIATES / ARCHITECTS

ST. CHARLES HISTORIC PRESERVATION COMMISSION

#### **CONTINUATION SHEET NO: 1**



### Address:

10 State Avenue

#### Remarks:

East side, showing original industrial building.

**ROLL NO. 4** 

NEGATIVE NO. 9

Block No. 28

**Building No. 2** 

#### Address:

10 State Avenue

## Remarks:

ROLL NO.

**NEGATIVE NO.** 

Block No. 28

**Building No. 2**